

## CORRECTION: M915 WEB PAGE

We printed a bad web site address in **PS 581** for the M915 Family of Vehicles. The correct address is <http://www.tacom.army.mil/dsa/pms/fp/m915/index.htm>. Use the site for info on training, operation, maintenance and fielding of these trucks.

## M936 Wrecker Hydraulics

You can service the hydraulic system of your M936/A1/A2 wrecker **without draining the reservoir** by installing shutoff modification kit, NSN 2590-01-415-9496. Instructions and drawings come with the kit. Repair and replacement instructions for kit components are found in TM 9-2320-272-24-2 (Jun 98) on Page 3-1154.

## AN/PRC-104B INSTRUCTION CARD

Need the operator instruction card for the AN/PRC-104B radio? CECOM has a limited supply and will send you one as long as they last. Send an E-mail to: [gloria.richardson@mail1.monmouth.army.mil](mailto:gloria.richardson@mail1.monmouth.army.mil)

## Compressed Air Cans

Need a quick, simple way to clean dust off your optics while avoiding the risk of scratches? Compressed air is the answer. Get cans of compressed air with these NSNs:

NSN 7930-01-	Size	Qty
411-9794	8-oz can	1
450-4378	10-oz can	1
398-2473	10-oz can	6
406-4055	12-oz can	1

Order the cans on a DD Form 1348-6 and put "NSN not on AMDF" in the REMARKS block.

## 5/10-KW TQG Selector Knob

Don't order the entire phase selector rotary switch, NSN 5930-01-386-0543, Item 36, Figure 13 in TM 9-6115-641-24P and Item 38, Figure 13 in TM 9-6115-642-24P, just to get the knob you grab to turn it. Order just the knob with NSN 5355-01-321-5354, instead of the entire switch, and save your unit \$400!

## CP-1252C Front Panel

Apache and Blackhawk mechanics, forget about sending in your CP-1252C/ASN-128B computer display unit (CDU) to depot for a new front panel assembly. The headshed has decided it costs too much. Now you can get a new front panel, NSN 1680-01-454-5154, and replace it at unit level. This info will be added to a TM to be published.

## Avenger RCU SMR Change

The SMR codes for the Avenger remote control unit's (RCU) mechanical sight and shoulder shafts (Items 7 and 9 in Fig 114 of TM 9-1440-433-24P) have been changed from XDOZZ (not stocked) to PAOZZ (stocked). That means you can now order them and you don't need to hold them back when you turn in an RCU. If you don't turn in all the parts with a broken RCU, it can't be repaired at depot until the missing parts are replaced. That wastes time, costs money, and hurts Avenger's readiness. Until the NSNs are assigned,

order the sight with part number 219F650 and the shaft with p/n 157D3327 on a DD Form 1348-6 with CAGE 05606 and RIC B64.

### DISTRIBUTION:

To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series