

MLRS SHOCK WASHER

Use NSN 5310-01-413-1037 to get the right flat washer for MLRS shock absorbers. The hole diameter of NSN 5310-00-928-1885, shown as Item 15 in Fig 9 of TM 9-1450-646-24P, is too small.

BRADLEY AIR CLEANER DOOR

Get a replacement door for your M2A2/M3A2 Bradley's air cleaner with NSN 5340-01-439-5897. The NSN was left out of Fig 130 in TM 9-2350-284-24P-1.

M992A2 Fuel Line Sealant

Stop using teflon tape, NSN 1015-01-255-4144, to seal fuel line threads and fittings on your M992A2 ammo carrier. The tape doesn't always prevent leaks, which can result in a fire hazard. Substitute sealing compound, NSN 8030-01-054-0740, instead. Pencil in the new NSN as Item 65 in Appendix D of TM 9-2350-293-20-2.

M989A1 HEMAT HELICAL SPRING

NSN 5360-01-390-6448 gets the helical spring for the service brakes of the heavy expanded mobility ammunition trailer. The NSN shown as Item 2, Fig 4, of TM 9-2330-368-14&P is no longer available.

HEMTT Ladder Pin

Need new holddown pins and chain for the ladder on your M983 HEMTT? You won't find them in TM 9-2320-279-24P-1. A new pin comes with NSN 5315-01-164-1782. The chain is made from NSN 4010-01-067-1700, which is available by the foot.

M109 HOWITZER LEAF SPRINGS

Need new leaf springs, NSN 5360-00-824-0522, for the breech on your M109-series SP howitzer? Be careful when you order. The unit of issue was just changed from 1 each to a package of 10.

HEMTT Electrical Connectors

Use NSN 5935-01-475-7130 and NSN 5999-00-338-9875 to get electrical connector plugs for the M978 HEMTT tanker. These NSNs replace the ones shown as Item 2 and 3 of Fig 114 in TM 9-2320-279-24P-1 w/Change 1.

M1113/M1114 HMMWV Rod Retainer

Order NSN 5360-01-474-9653 to get the HMMWV door subassembly's rod retainer clip-clevis. The parts info shown as Item 14, Fig 170 of TM 9-2320-387-24P is wrong.

M939/A1/A2 BLACKOUT LAMP

NSN 6220-01-094-1440 gets the 5-ton truck's blackout lamp. The NSN shown as Item 1, Fig 141 of TM 9-2320-272-24P-1 gets the wrong lamp.

M916/M20 FIFTH WHEEL

NSN 2510-01-192-0631 gets the fifth wheel assembly for the M916 and M920 tractor trucks. Use compensator ramp, NSN 2510-01-305-6284, to go with the assembly. Do not mount a new fifth assembly with an old ramp. These NSNs replace the ones shown as Item 1 of Figs 230 and 231 in TM 9-2320-273-24P.

PLS Trailer Load Binder

NSN 5420-00-529-4427 gets the BII load binder for the M1076 PLS trailer. The parts info shown for Item 5, Page C2 of TM 9-2330-385-14, is wrong.

PLS Air Horn Kit

NSN 6350-01-460-5600 gets an air horn that's louder than the truck's electric one. The kit includes all the parts shown in Figure 240 of TM 9-2320-364-24P-1. Installation instructions come with the kit.

AIRCRAFT COVERS

RoLin Industries Inc. (Windshield Buddy) provides aircraft covers for all kinds of weather and locales for OH-58/AH-64/CH-47/UH-60 aircraft. NSNs for covers for AH-64s are accessible at

<http://www.windshieldbuddy.com>

You can call 1-888-667-9455 or e-mail

sales@windshieldbuddy.com

Their address is:

RoLin Industries Inc.
634 Lovejoy Road
Ft Walton Beach, FL 32548

 RoLin
Industries, Inc.

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

Would You Stake Your Life ^{right now} on the Condition of Your Equipment?