

ELSE...

## DISTRESS MARKER LIGHT LEAKAGE

SERGEANT FUENTES, I'VE GOT A BAD DISTRESS MARKER TO TURN IN.

PROBABLY A BAD IR HOUSING. WE'LL GET IT REPLACED.

**ELSE** techs, if you've noticed visible light coming from the housing of a SDU-39/N distress marker strobe light, you have a defective infrared red (IR) housing.


Inspect the light marker data plates for NSN 6230-01-411-8535 or NSN 6230-01-448-8340, and contract numbers SPO500-98-D-2710 or SPO560-00-F-0162.

If you have any of these light markers, request replacement housings by calling Ann Schrage, Defense Supply Center Philadelphia, at DSN 444-8103 or (215) 737-8103, or email her at [aschrage@dscpc.dla.mil](mailto:aschrage@dscpc.dla.mil).

Include in the request your unit, number of replacement housings needed, unit identification code, applicable NSN and a mailing address with a POC.

When you receive the replacement housings, remove the defective housings and return them to:

Industries For the Blind  
6350 Burnt Poplar Road  
Greensboro, NC 27409-9710



Install the new housings on the body like it says in PM ACIS message (AIS02-02) and test for light leakage at all angles. If no light leaks, you're good to go. Check out all the details in the PM ACIS message.