



IT'S IN THE CARDS



If your M1A2 SEP or M104 Wolverine still has any of the older Army embedded GPS receiver (AEGR) circuit cards, NSN 5998-01-463-1005 (PN 12438580 or 110100), turn them in right now!

That includes any AEGR cards found in the turret mission processing unit (TMPU) and the improved launch electronics control unit (ILECU) during repair. Those cards need to be upgraded to the new version, NSN 5998-01-496-5901 (PN 12438580-2).

Turn in unserviceable cards following your regular turn-in procedures. Your TACOM LAR can help. Serviceable AEGR cards can be exchanged for the new version through the Abrams Material Fielding Team office. Contact Mike Athey, DSN 738-7731 or (254) 288-7731, or Abbey Castro, DSN 566-6564 or (254) 288-6564. Or send an email to:

michael.athey@hood.army.mil or
abimael.castro@hood.army.mil