

ELSE...

CAN'T GET HELMET EARCUP ASSEMBLY

I'M GLAD
THIS NEW
EARCUP IS
WORKING!

GOOD THING WE
GOT THE MESSAGE
BEFORE YOU
ORDERED THE WRONG
NSN IN THE TM...

...OR I'D
STILL BE
SITTIN' ON
THE SHELF
NMC!




ELSE techs, are you having trouble getting the earcup assembly, NSN 8415-01-395-6841, for your HGU-56/P aircrew integrated helmet system (AIHS)?

The problem is an incorrect SMR code listed for Item 12 in Figure F-2 of TM 1-8415-216-12&P that told you to order the assembly.

HERE'S WHAT YOU
NEED TO DO.
CANCEL YOUR
REQUISITIONS AND
ORDER THESE
SEPARATE ITEMS...



- Earcup assembly shell, NSN 5965-01-390-8873, Figure F-5, Item 1
- Ear cushion, NSN 5965-01-392-6179, Figure F-5, Item 2
- Receiver retainer, NSN 8415-01-330-6618, Figure F-5, Item 3
- Seal assembly, earpad, NSN 8415-01-074-1622, Figure F-5, Item 4



Make a note until the TM is updated and check for all aviation life support information on the PM Air Warrior web site at:

<https://airwarrior.redstone.army.mil>

You'll have to apply for a username and password for access.