


NEW PLATES FOR UPGRADES



ARE THERE ANY
M1131 FSV STRYKERS
IN YOUR UNIT?

THEN YOU
NEED TO
PAY *CLOSE*
ATTENTION!

All M1131 Fire Support Vehicles have been upgraded to FSV/FS3s. The upgrade included the addition of the long range advanced scout surveillance system (LRAS3) and the laser designator module (LDM).

With the upgrade, the vehicle's NSN and part number have changed. The new NSN is 2355-01-528-1274 and the new part number is 12501485. All designated property book officers and hand receipt holders need to update their document registers to reflect the change.

PM-Stryker Brigade Combat Team (SBCT) is working out a plan to have all vehicle data plates replaced, either by providing the plates to each installation or by having a field service representative visit each location to install them.



ONCE YOU'VE UPDATED
THE HAND RECEIPT, NOTIFY
PM-SBCT SO THEY KNOW
WHERE THE DATA PLATES
ARE NEEDED.

JUST SEND
AN EMAIL TO:

us.army.mil