

# ARMOR WEAKENS CAB MOUNTS



**F**ront and rear cab mounts and the rear cab mount structure on the Freightliner M915 family of vehicles (FOV) have been stressed with the application of the add-on armor kit. The cab could separate from the chassis or steering loss could occur if this problem isn't fixed.

TACOM SOUMs 06-022 and 07-005 addressed this problem and gave repair guidance per the TM and an engineering solution, so this isn't a new issue. **But since there's cab damage that those repairs can't correct, mechanics must use the procedures given in TACOM SOUM 07-011 immediately.** Then make weekly checks to ensure the cab is holding up.

For details, see the mandatory procedures online:

[https://aeaps2.ria.army.mil/commodity/soum/tacom\\_wn/07/soum07-011.html](https://aeaps2.ria.army.mil/commodity/soum/tacom_wn/07/soum07-011.html)

Or contact TACOM's

at DSN 312-786-7547, (586) 574-7547, or

[@us.army.mil](https://twitter.com/us.army.mil)