



## M1114 HMMWV Underbody Screw

The hex screw for your M1114's front passenger side underbody shown as Item 11 in Fig 194 of TM 9-2320-387-24P has the correct part number. The NSN is wrong, however. Replace it with NSN 5305-01-436-6377.

## HELMET HARNESS TESTER

ALSE folks, here's some good news! Your integrated helmet and display system (IHADSS) has a new tester for the helmet's new IR harness. NSN 4931-01-534-1228 brings you the tester. You can use the tester on the old harness as well.

## COMMUNICATION EARPLUG KIT

All new HGU-56/P helmets now come with the communication earplug (CEP) already installed. If you have a helmet that doesn't have a CEP installed, you can order the communication earplug kit with NSN 5965-01-474-5654.

## Out with the Old BB-390B/U, In with the New BB-2590/U

There are two rechargeable batteries that can be used in your BA-5590 powered equipment like the ASIP SINGARS. One is the BB-390B/U, NSN 6140-01-490-4317. The other is the BB-2590/U, NSN 6140-01-490-4316. Order the BB-2590 and not the BB-390. Why? They're close in cost and the BB-2590/U is more powerful and lighter. But more important for the next few months, the BB-390 is out-of-stock while the BB-2590/U is ready to ship today!

## FIBER OPTIC CABLE NSNs

Order 300 meters of CX-13295/G fiber optic cable with NSN 6020-01-220-5435. Order 1,000 meters with NSN 6020-01-208-1147.

## Upgrading M7 FRS

If your M7 forward repair system (FRS) has a serial number from 0001 to 0743, you need to upgrade its tool load and/or data plate. M7's with tool load P/N SC4940-95-E41 (formerly P/N RIA149000), which is Granger, need to get tool load SC4940-95-E42, which is Snap On, and a new data plate, NSN 4940-01-533-1621.

If you already have SC4940-95-E42 (Snap On), you just need the new data plate. To receive the tool load and/or data plate, send TACOM-RI the following info:

- M7 serial number
- unit name
- ship to address
- POC with phone number and email

Email it to [at@us.army.mil](mailto:at@us.army.mil)

## RTCH Central Lube System

The project manager's office (PMO) at TACOM LCMC is looking for Kalmar RT 240 rough terrain container handlers that need a central lubrication system installed on the vehicle for **FREE**. Contact the PMO by writing to at this e-mail address:

[@us.army.mil](mailto:at@us.army.mil)

## AIRSAVE VEST INFORMATION ON THE NET

The Army is a user of the Navy's AIRSAVE vest and other aviation life support equipment. If you need TM information on AIRSAVE, you can access the aircrew systems program office online: <https://home.navy.mil/pma202>

To access the site, you'll need CAC card certification and will have to apply for an email login and password.

## HEMTT ENGINE WIRING HARNESS UPDATE

Get the -A2 and -A2R1 model HEMTT's DDEC 4 engine wiring harness (for HEMTTs other than wreckers) with NSN 6150-01-508-2486, PN 3462712, and CAGE 45152. This applies to the M1120A2 and M1120A2R1 HEMTT LHS trucks, too, but they aren't listed in the *usable on* codes in the HEMTT IETM, EM 0232.

Your M984A2 and M984A2R1 wrecker's DDEC 4 engine wiring harness comes with NSN 6150-01-508-2487, PN 3462713, and CAGE 45152. Use the sticky note feature in your HEMTT IETM to update Fig 543.

## Up-Armored HMMWV Fuel Strainer Element

Need the strainer element that's part of the filler neck in the fuel filler pipe assembly of your up-armored HMMWV? You can't get it using the NSN listed for Item 23 in Fig 29 of TM 9-2320-387-24P. Make a note to get it with NSN 4730-01-311-4294.

## ASV Annual Service Kit

Need the annual service kit for the armored security vehicle? It comes with NSN 4910-01-526-7869.

## EMI FILTER FOR IMG MRAP FIRE SUPPRESSION SYSTEM PREVENTS ACCIDENTAL DISCHARGE

TACOM MAM 08-012 told you that users of International Military and Government (IMG-MaxxPro) Mine Resistant Ambush Protected vehicles (MRAP), NSN 2355-01-553-4634, were having accidental discharges of the cabin fire suppression system (FSS) bottles. Some of the vehicles arrived in Theater with the cabin FSS bottles already discharged.

Now we know the cause of this problem is electromagnetic interference (EMI). And you can solve this problem by using an EMI filter. The IMG FSS vendor, Lehavot, will provide free EMI filters for retrofit on vehicles in Theater beginning in mid-April 2008.

IMG field service reps will get them to you, and your unit mechanic can install them. Eyeball TACOM MAM 08-028 online for more details:

[https://aeps2.ria.army.mil/commodity/mam/tacom\\_wn/08/mam08-028.html](https://aeps2.ria.army.mil/commodity/mam/tacom_wn/08/mam08-028.html)

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

# Would You Stake Your Life <sup>right now</sup> on the Condition of Your Equipment?