


Exhaust Hose Assembly




OPERATORS, THE EXHAUST HOSE ON THE LIGHTWEIGHT WATER PURIFIER (LWP) IS KNOWN TO LEAK AFTER CONTINUOUS USE.



THAT'S A REAL PROBLEM DURING COLD WEATHER OPERATION WHEN FUMES ACCUMULATE INSIDE A HEATED TENT!

SO-O-O, HAVE YOUR MECHANIC REPLACE A LEAKY HOSE WITH A NEW HOSE ASSEMBLY (THE HOSE AND CLAMP) THAT COMES WITH NSN 4720-01-567-1009.

THE HOSE IS SHOWN IN FIG 7 OF WP 0018-6 OF TM 10-4610-310-13.



YOU CAN GET THE HOSE ASSEMBLY **FREE** BY CONTACTING THE LWP ITEM MANAGER AT DSN 786-4146, (586) 574-4146, OR BY EMAIL:

@us.army.mil