


GOOD HEAVENS, HALF-MAST!
HAVE I REALLY BEEN SHARING
PREVENTIVE MAINTENANCE INFO WITH
THE TROOPS FOR THAT LONG?!



CORPORAL *Connie Rodd's*
BULLETIN BOARD



1942

M872/A1/A2 Brake Chamber Dust Cap

Use NSN 2530-01-367-6668 to get a dust cap for the air brake chamber on your M872/A1/A2 34-ton flatbed semitrailer. It replaces NSN 3040-01-065-2021, which we listed on Page 16 of PS 695 (Oct 10):

<https://www.logsa.army.mil/psmag/archives/PS2010/695/695-16.pdf>

M24 BINOCULARS NSNs

If you use the L3 version of the M24 binoculars, NSN 1240-01-499-3547, there are now three replacement items that can be ordered:

- objective lens cap, NSN 6650-01-589-0552
- eye lens cap, NSN 6650-01-589-0551
- webbing strap, NSN 5340-01-589-3985

M1079 FMTV CARGO NET

Get an interior cargo restraint net for the shelf or floor area of the M1079 FMTV's shop van by using NSN 3940-01-477-7081. This net helps secure cargo from bouncing around inside the vehicle. A three-position molded nylon clamp locks a clinching line around the entire net. Each net comes with a storage bag and attachment instructions.

MRAP M-ATV CV Joint Kits

When the CV joint boot gets ripped or torn on the M-ATV's front half-shaft, use NSN 2520-01-474-5708 to get a replacement kit that includes the boot and clamps. For the entire half-shaft assembly, which includes the outer CV half-shaft, deflector, shaft yoke, boot, clamps and tube shaft, use NSN 2520-01-474-5707. Both of these NSNs are missing from TM 9-2355-335-24P.

M978A4 HEMTT TANKER PUMP

To get the HEMTT tanker's primary pump, use NSN 4320-01-579-1044. This NSN includes the pump assembly w/motor and replaces the parts info shown as Item 1 in Fig 433 of TM 9-2320-326-14&P (EM 0288).

M777A2 Parts Update

Operators and mechanics, make note of the following NSN updates to TM 9-1025-215-24&P (EM 0274) for the M777A2 towed howitzer: The 300-320mm spanner wrench in Fig 20 now has an NSN. Order it with NSN 5120-12-381-2036 (PN 54841). The accumulator seal kit, NSN 1090-99-730-6603, in Fig 91 has changed to NSN 1680-99-226-6690 (PN AMP 09 00 40000). The NSN for buffer seal kit was incorrectly listed in Fig 9589. The correct NSN is 1090-99-169-4703, not 4730. These changes will be added during the next update to the TM.



MRAP Arm Lift Kit

The MaxxPro Plus ambulance arm lift kit comes with NSN 2590-01-583-1145. This kit prevents the patient's head (and/or spine) from bumping into the vehicle's upper litter support arm. Go to the Army Electronic Product Support (AEPS) website for the kit's parts and installation instructions. You'll need your AKO login and password to access it:

https://aeps2.ria.army.mil/commodity/gpm/tacom_wn/CASEVAC-Kit-ArmInstall.pdf

AR 700-16 Revised

A major revision to AR 700-16, *U.S. Army Ammunition Management in the Pacific Theater*, went into effect in Nov 2010. The revision covers materiel management and explosive ordnance disposal. It's available on the Army Publishing Directorate's website:

http://www.apd.army.mil/pdf/files/r700_116.pdf

PUB UPDATES ARMY SUSTAINMENT

TRADOC Pam 525-4-1, *The United States Army Functional Concept for Sustainment 2016-2028*, was revised in Oct 2010. The revision covers topics such as homeland defense and civil support. Check out the full deal:

<http://www.tradoc.army.mil/tpubs/pams/tp525-4-1.pdf>

Turn In M578 Recovery Vehicles

M578 recovery vehicles are no longer supported by the Army. Units need to take them off their property books and turn them over to their nearest DRMO/DRMS. Also, this vehicle system has no secondary items in the supply chain. For more information call TACOM's major item manager, Ms. Cynda Peter, at DSN 786-5687 or (586) 282-5687, or contact her by email: cynda.peter@us.army.mil

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

Would You Stake Your Life ^{right now} on
the Condition of Your Equipment?