

## GCSS-ARMY MATERIALS AVAILABLE

Units, to get the latest Global Combat Support System-Army (GCSS-Army) informational DVDs, brochures or flyers, send an e-mail request with your physical address (no P.O. Boxes) and complete contact information to:

[jim.mcdonough@us.army.mil](mailto:jim.mcdonough@us.army.mil)

## 2011 Defense Logistics Agency Customer Assistance Handbook

The 18th edition of the DLA Customer Assistance Handbook is available online and in hard copy for DLA customers. To register to access the online version or to order a hard copy, visit:

[http://www.dla.mil/dla\\_customerpub/communications.aspx](http://www.dla.mil/dla_customerpub/communications.aspx)

For additional information, email: [handbook@dlia.mil](mailto:handbook@dlia.mil)

## HMMWV Engine Oil Pressure Changes

The current engine oil pressure requirements in all HMMWV national maintenance work requirements (NMWRs) and technical manuals have been revised.

Operating oil pressure requirements for engine rpm above idle should be changed from 30-50 psi to 25-65 psi and 30 psi should be changed to 25 psi. Minimum oil pressure at idle will remain 10 psi. Make a note until updates are made.

## SEE Drive Shaft Boot

To get the rubber, one-piece boot for the front and rear drive shafts on the small emplacement excavator (SEE), use NSN 9390-01-240-4662. It's shown as Item 5 in Fig 126 and Item 24 in Fig 127 of TM 5-2420-224-24P-1. Do not use any commercial split-type boot. The SEE has a fording requirement that prevents the use of a split-type boot.

## QUICK FIX FOR VIEWING PS ONLINE

Has your computer been upgraded from Adobe Reader 9® to Adobe Reader X® recently? Then you've probably noticed a problem when trying to open a copy of *PS Magazine* online.

There is an incompatibility problem between Adobe Reader X® and Internet Explorer 7® (IE 7®) that causes a failure when trying to open large PDF files like *PS Magazine*. Adobe is looking into the problem.

Until a solution is found, there are two work-arounds to try. First, use the Mozilla Firefox® Internet browser to access *PS Magazine*. Firefox® is a bit slower than IE 7®, so be patient until the file opens.

Second, you can use IE 7® to download PS issues directly to your hard drive. Just right mouse click on the cover for the issue you want, choose Save Target As and select where you'd like to save the issue on your hard drive. Then open the issue using Adobe Reader X®.

Starting with PS 704 (Jul 11), the red box links (Click here for a copy of this article to save or email) at the bottom of each article were changed to hotlinks. Even if you've downloaded the issue to your hard drive, you can still click on the link to open that individual article in IE 7®.

The red box links in issues prior to PS 704 will not work if you've downloaded the issue to your hard drive. They were designed to open files on the PS server and will only work when viewing the issue in IE 7® or Firefox®.

## TEST AN/UDR-13 FOR BEEPING

Some AN/UDR-13 radiacmeters have a software problem that causes them to beep—and you can't turn off the beeping. That could be disastrous in a combat situation where the beeping could alert the enemy. So it's critical you CBRN specialists check to see if any of your AN/UDR-13s are beepers, especially if their serial numbers range from 6000C to 33000C.

Turn them on and let them operate away from a radiation source for at least 20 minutes. If one beeps, mark it so you know not to use it in a situation requiring silence. CECOM is working on a fix, which PS will let you know about.

It's OK to use the beepers in non-combat situations. They still accurately measure radiation.

## CAIMAN MRAP DAS Battery

Use **only** NSN 6140-01-569-6570 when you need to order a battery for the door assist system (DAS) on CAIMAN MRAPs. Do **not** replace the DAS battery with one that comes from a different vehicle system. If you use the wrong battery, the DAS will malfunction. Then the rear door won't open or close properly—meaning you won't be able to get in-or-out of the vehicle!

## M870A1 Wood Decking Kit

Use NSN 5510-01-540-5724 to get a complete wood decking kit for the 40-ton lowbed semitrailer. Make a note until this NSN is added to Fig 29 of TM 5-2330-378-14&P.

## Calibration Changed for JCBRAWM Radiacmeter

If your unit has the M329 Joint Chemical Biological Radiological Agent Water Monitor (JCBRAWM), you need to change the calibration date for its IM-263/PDR-77 radiacmeter, NSN 6665-01-348-4688. The radiacmeter's calibration date has been extended three years from the DATE CALBR listed on the radiacmeter. This change applies only to the -PDR-77s used with JCBRAWM.

## M939/A1/A2-Series Wheel Stud Nut

A nut for the wheel stud nut for the M939/A1/A2-series 5-ton truck comes with NSN 5310-01-445-6872. This NSN replaces the one shown as Item 7 in Fig 292 of TM 9-2330-272-24P-1.

## M939/A1/A2 Axle Gasket

To get a non-asbestos gasket for the top access cover on your M939 5-ton's axle differential, use NSN 5330-01-514-6882. This NSN replaces the one shown as Item 4 in Fig 240 of TM 9-2320-272-24P.

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

Would You Stake Your Life <sup>right now</sup> on the Condition of Your Equipment?