


WHILE YOU'RE AT IT, ALSO CHECK THE FIRING PIN ASSEMBLY FOR THESE PROBLEMS...



- retaining pin spring jamming in the housing on the lock assembly
- retaining pin knob not turning or turning with difficulty



Retaining pin knob hard to turn?

If the firing pin is defective, turn it in to Contractor Logistics Support for free replacement.


Questions? Contact TACOM's Jason Nickert at DSN 786-6720, (586) 532-6720, or email:

[jason.j.nickert.civ@mail.mil](mailto:jason.j.nickert.civ@mail.mil)

For more information, see TACOM ground precautionary action (GPA) message 12-018:

<https://tulsa.tacom.army.mil/SAFETY/message.cfm?id=GPA12-018.html>

PS END



WAIT!  
I CAN'T  
GO YET!

THEY DIDN'T  
INCLUDE MY  
COEI!



## COEI Stays with M119A2

If your M119A2 howitzer is being shipped out or transferred to another unit, its components of end item (COEI) must go with it. COEI cannot be separated from the end item.

M119A2 COEI include the breech block, M187 mount and jack strut.

Basic issue items (BII) are another story. They can be packaged and shipped separately from the M119A2.

For a complete list of the M119A2's COEI and BII, see WP 0051 in TM 9-1015-252-10 (Sep 10).