


Keep Your M934s For Now



If your unit has the Direct Support Electrical System Test Set (DSESTS), hang on to your M934-series trucks for the time being, even though the Army is replacing all M900-series 5-ton vehicles with FMTVs.

That's because the M1087 FMTV isn't approved yet as a DSESTS prime mover. Concerns about possible electrical problems, weight and balance issues and cabinet space limitations are the reasons why.

Units can't make modifications to the M1087 without an MWO and there isn't an MWO available yet. A documented load plan and procedures for installing DSESTS in M1087s are still in the works, too.

Until those issues are worked out, and TACOM comes up with an MWO, don't turn in your M934s. Also, you'll need to reuse the DSESTS storage cabinets when switching to the M1087, so hang on to those, too.

Questions? Contact one of the TACOM POCs below:

Kevin Craft, (586) 282-3597, DSN 786-3597 or email:

kevin.t.craft.civ@mail.mil

Douglas Wlodarski, (586)282-3064, DSN 786-3064 or email:

douglas.a.wlodarski.civ@mail.mil

Shiraz Ally, (586) 282-2352, DSN 282-2352 or email:

shiraz.ally.civ@mail.mil