

# DON'T STEP THERE!

The M9 ACE's ejector hydraulic cylinder rod looks like a handy step, especially when you step down into and around the bowl to check the vehicle's compensation pump or look for a leak in the valve bank.

Problem is, your muddy boots can scratch the cylinder rod's surface. A scarred rod tears up the cylinder's seal when the ejector moves back and forth. That causes a hydraulic leak.

Excess hydraulic oil on the cylinder rod is a sure sign the seal is shot.

So save costly repairs and downtime by staying off the cylinder rod when you need to get inside the earthmover's bowl.



HEY! I'M  
NOT A STEP,  
BUB!