



MISROUTED WIRING WARRANTS WARRANTY




UH-OH! That's what we sometimes hear when a mistake is made. But it's not until the mistake is found that we can focus on the solution.

A manufacturing error resulted in the wiring harnesses being routed directly across the top of the hydraulic distribution manifold in some HEMTT -A4 trucks. Routed this way, the wiring harness might start a fire.



THE SOLUTION IS FOR YOU MECHANICS TO INSPECT ALL HEMTT -A4 HYDRAULIC DISTRIBUTION MANIFOLDS. MAKE SURE THAT NO WIRING HARNESSES ARE ROUTED OVER THE TOP OF THE MANIFOLD.



If you find any, contact Oshkosh Corporation to schedule the vehicle for repair. They're at: WarrantyClaims@defense.oshkoshcorp.com

Oshkosh will provide the required parts and labor to fix the trucks at no cost to your unit. They'll repair the vehicles as part of a retrofit effort that includes rerouting the wiring harnesses.

Need more assistance? Contact your TACOM LCMC logistics assistance representative (LAR) or your state surface maintenance manager.