

MK 19 Machine Gun...



I'M NOT GONNA STOP RUNNING UNTIL YOU AGREE TO DROP BOTH MY CHARGING HANDLES!

DROPPING JUST ONE HANDLE CAN DAMAGE ME!

The Rundown on Stopping Runaways

Both the MK 19 machine gun's TM 9-1010-230-10 and -23&P say the way to stop a runaway MK 19 is to lower one of the charging handles.

Unfortunately, that method can damage the bolt, charger housing or charger assembly. So the most effective and safest way to stop a runaway is to lower **both** charging handles. Also lower both charging handles while doing the function test during PMCS.

One way to definitely not stop a runaway MK 19 is trying to break the ammo belt. That can seriously injure your hands.



Lower both charging handles to stop runaway MK 19



ATTENTION SNIPERS!

IF YOU USE THE XM107 LONG RANGE SNIPER RIFLE OR THE M110 SEMIAUTOMATIC SNIPER SYSTEM, LISTEN UP!

All XM107s should have been converted to the M107 by now. If you still have an XM107, turn it in ASAP. An XM107 is stamped XM107. If it has been upgraded, the X will be lined out.

All M110s with serial numbers below 1000 should have had their trigger assemblies replaced. If yours hasn't, turn it in. If you're not sure if the trigger has been replaced, contact TACOM's David Tipp at DSN 786-1256, (586) 282-1256, or email: david.i.tipp2.civ@mail.mil

You can also get turn-in instructions for both systems by contacting Mr. Tipp.