


# Test IR Switch

REPORTS ARE COMING IN FROM THE FIELD THAT THE IR ADJUST SWITCH FOR THE AN/PED-5 LASER TARGET LOCATOR MODULE (LTLM) IS SOMETIMES FAILING.

THAT'S WHY YOU NEED TO MAKE A POINT TO **CHECK THE SWITCH BEFORE YOU GO TO THE FIELD** FOLLOWING THE PMCS IN TM 9-1240-455-10.

IF THE SWITCH **DOESN'T** ADJUST THE THERMAL IMAGE, TURN IN THE AN/PED-5 FOR REPAIR.



Test IR adjust switch during PMCS

**QUESTIONS?** →

CONTACT TERRY MONROE AT (703) 704-1067 OR EMAIL: [terry.l.monroe2.ctr@mail.mil](mailto:terry.l.monroe2.ctr@mail.mil) OR ENGELS ARIAS AT (536) 282-1230 OR EMAIL: [engels.d.arias.civ@mail.mil](mailto:engels.d.arias.civ@mail.mil)

## Does Your TMWSS/SEW Need a Spare Tire?

IF YOUR TRAILER MOUNTED WELDING SHOP SET (TMWSS)/SHOP EQUIPMENT, WELDING (SEW) NEEDS A SPARE TIRE, THEN THERE'S AN MWO JUST FOR YOU.



MWO adds spare tire to TMWSS/SEW

MWO 9-4940-567-50-1 ADDS TWO KITS: SPARE TIRE SUPPLEMENTAL KIT, NSN 2590-01-587-6333, AND SPARE TIRE KIT, NSN 2590-01-578-5628.

THE MWO SHOULD BE DONE THROUGH YOUR LOCAL MWO COORDINATOR.

THE TMWSS/SEW IS COVERED BY TM 9-4940-567-13&P (OCT 03, W/CH 2, APR 10).

**QUESTIONS?** CONTACT TACOM'S ROBERT CLINE AT (536) 282-1650 OR EMAIL: [robert.l.cline24.civ@mail.mil](mailto:robert.l.cline24.civ@mail.mil)