

# Connie's Post ★ SCRIPTS

## MaxxPro Dash ESC Instructions

Instructions for operation of the MaxxPro Dash's electronic stability control (ESC) were left out of TM 9-2355-441-10. Download a copy of the instructions at:

[https://tulsa.tacom.army.mil/Maintenance/download.cfm?filename=mam/tacom\\_wm/MaxxProESC.pdf](https://tulsa.tacom.army.mil/Maintenance/download.cfm?filename=mam/tacom_wm/MaxxProESC.pdf)

Or request a copy from Half-Mast:

[usarmy.redstone.logsa.mbx.psmag@mail.mil](mailto:usarmy.redstone.logsa.mbx.psmag@mail.mil)

## GCSS-Army Reminder

Remember to check the GCSS-Army website for alerts, updated fielding and training schedules and other important info. Visit: <https://gcss.army.mil/>

Or sign up to get automatic notifications at: <https://gcss.army.mil/Support/register.aspx>

## M1A1 Phone Handset NSN

Get the phone handset for your M1A1 tank with NSN 5965-01-549-6390. NSN 5965-00-043-3463, which is Item 1.1 in WP 0499 of TM 9-2350-264-10-3 (Sep 11 w/Ch 3, Jan 15), is a terminal item.

## A4 HEMTT Radiator Cap NSN

Get a new radiator cap for your A4 HEMTT with NSN 2930-01-570-8498. The cap was mistakenly left out of TM 9-2320-326-14&P in IETM EM 0288 (Oct 08), so make a note until the IETM is revised.

## Backhoe Loader A/C V-belt

Get a new air-conditioner V-belt for your backhoe loader (BHL) with NSN 3030-01-641-4944 (PN 87393292). This replaces PN 87429954, which is shown as Item 9 in Fig 160 of TM 5-2420-231-24P (Jun 13).

## 621G Scraper EMS Alarm

Get the 621G scraper's EMS fault alarm with NSN 6350-01-423-9687. NSN 6350-01-426-9687, which is listed as Item 31 in Fig 162 of TM 5-3805-296-24P (Jun 13), is the wrong NSN.

## SEND US YOUR PS TOAST

In June 2016, *PS Magazine* celebrates its 65th year. Like most magazines, we work months ahead, so we're already seeking "happy anniversary" stories. Operators, mechanics, supervisors and commanders, tell us if *PS* ever saved your bacon or just plain made your day. Got a favorite article or character? Did our reader service answer a burning question? We'll feature some reader toasts in a special edition. Put "PS Toast" in the subject line and email:

[usarmy.redstone.logsa.mbx.psmag@mail.mil](mailto:usarmy.redstone.logsa.mbx.psmag@mail.mil)

## BLACK HAWK'S DACU STOCK SUSPENDED

All serviceable stock for the UH/HH-60M Black Hawk's data acquisition concentrator unit (DACU), NSN 6610-01-557-9608, is suspended until further notice. The NSN has two part numbers, 70600-03811-101 and 280930. You can find all the details to identify bad DACUs in aviation safety action message (ASAM) H-60-15-ASAM-05. A solution is in the works to fix the problem. Got questions? Contact the item manager, Heri Rodriguez, DSN 746-5269, (256) 876-5269 or email:

[heriberto.rodriguez2.civ@mail.mil](mailto:heriberto.rodriguez2.civ@mail.mil)

## OCP Transition Pocket Guide

Grab the SMA-approved guide that covers the Army's new Operational Camouflage Pattern (OCP). The PDF has full-color pictures, making it a handy reference. To get it, you'll need a milSuite account and S1NET membership. Follow the instructions to join at <https://www.milsuite.mil> next go to <https://www.milsuite.mil/s1net> and pick the "Join S1NET" widget on the upper left side of the page. Approval is automatic. Then get the guide at:

<https://www.milsuite.mil/book/docs/DOC-212321>

## FMTV INTERCONNECTING BOX REVISITED

Page 14 of PS 753 (Aug 15) provided an email address for requesting a free FMTV interconnecting box. Unfortunately, a period was left out of that address. If your FMTV's serial number is 100,001 or above, you can get the free interconnecting box, minus shipping costs, by sending an email to:

[christopher.grasso@dyn-intl.com](mailto:christopher.grasso@dyn-intl.com)

## 120M Grader Wiper Motor

Get the right-side (curb-side) wiper motor and assembly for your 120M road grader with NSN 2540-01-455-4834. The motor is missing from Fig 123 in TM 5-3805-293-24P (Mar 11) and is not interchangeable with the left-side wiper motor.

## Green CSS-VSATs Need Reset, Upgrade

Units, all remaining green Combat Service Support Very Small Aperture Terminals (CSS-VSATs), NSN 5895-01-526-8838 (LIN J97857), need to go to Reset and also need to be upgraded. ALARACT 123/2015 has specific instructions. You'll find ALARACTs on AKO. Folders are filed by year. Grab your CAC and go to: <https://www.us.army.mil/suite/page/550282>

## Attention: LIW Users in Theater

To get Logistics Information Warehouse (LIW) technical assistance in theater from the Logistics Support Activity (LOGSA), email:

[usarmy.redstone.logsa.mbx.service-desk@mail.mil](mailto:usarmy.redstone.logsa.mbx.service-desk@mail.mil)

For theater training support, email:

[usarmy.redstone.logsa.mbx.training-support-to-theater@mail.mil](mailto:usarmy.redstone.logsa.mbx.training-support-to-theater@mail.mil)

**Note:** The former support email address no longer works. Any email sent there will *not* be forwarded.

[\(usarmy.redstone.logsa.mbx.arfor-gen-support@mail.mil\)](mailto:(usarmy.redstone.logsa.mbx.arfor-gen-support@mail.mil))

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for the TB 43-PS-Series.

Would You Stake Your Life <sup>right now</sup> on  
the Condition of Your Equipment?