# Down On Your Luck?




While it won't cause you 7 years of bad luck, damaging the head mirror on your tank's dual axis head assembly (DAHA), NSN 1240-01-362-1914, can cost your unit some extra bucks.

The problem comes when a damaged DAHA is sent in for repairs. Even when you send the assembly in its shipping container, NSN 8145-01-476-4131, loose pieces of metal, dust and loose desiccant can scratch the head mirror. The DAHA arrives even more damaged than when it was shipped.

Stop that extra damage by first wrapping the head mirror in lens paper, NSN 6640-00-436-5000, followed by a layer of cardboard. Hold the coverings in place with masking tape.

Add a small bag of desiccant, NSN 6850-00-264-6571, to the shipping container to protect against moisture and the DAHA should arrive the same way it was shipped.