NEW NOSECUP VALVE SEAT AND INLET VALVE



Good news, NBC NCOs. You no longer have to fool with using RTV silicone to glue in a new nosecup valve seat assembly on the M40/M42-series masks. And there's a new NSN for the inlet valve body.

There is now a valve seat assembly that snaps into place. NSN 4240-01-496-2844 (P/N 5-1-2748) brings 10 top and bottom portions of the assembly and an instruction sheet showing how to do the task. See SBCCOM's supply advisory message 03-06-004 for more info.

New nosecup valve seat assembly just snaps into place



NSN 4820-01-509-5498 is new NSN for inlet valve body



If you have questions, contact SBCCOM's Kevin Joubert at DSN 584-6147/(410) 436-6147 or email:

kevin.joubert@sbccom.apgea.army.mil

The NSN for the inlet valve body is now NSN 4820-01-509-5498. Its part number remains 5-1-1054.