

Dear MSG Half-Mast,

I have inspected many units that use the ***newest*** AN/PVS-14 monocular night vision device (MNVD). I have been surprised at how many of these MNVDs don't have the threaded eyecup adapter ring or have a loose one ready to back off and fall off.

What's with these non-threaded adapter rings? Should soldiers using the AN/PVS-14 check these rings for threads?

SFC D. A. J.

Dear Sergeant D. A. J.,

You've grabbed the brass ring and identified a problem that needs to be solved. A batch of eyecup adapter rings got in the supply system without threads. The supply system has been purged of these non-threaded rings so turn them in and order new threaded rings with NSN 5855-01-466-7891. Don't try to glue the non-threaded rings in place! They are a little bit bigger than the threaded ones and glue won't hold them.

Half-Mast

Order threaded rings with NSN 5855-01-466-7891