PS Magazine Index No. 70, 2014

Subject	Issue/Pg	
AIR CONDITIONERS		
60K-BTU IECU--Cover, storage bag	737	45
60K-BTU IECU--Replaces FDECU	743	61
60K-BTU IECU--Storage of components	738	48
AIRCRAFT ARMAMENT SUBSYSTEMS		
M230--Cleaning, lubing, sideloader, hydraulics	737	25
M230--Sideloader, cannon plug, lock wires...	742	24
AIRCRAFT, GENERAL		
DA-authenticated TMs only	745	26
Electrical system circuit breaker lockout	743	23
Fire extinguisher use, number needed	735	22
FMs being converted to TMs	737	61
Forms, TMs, FCC, signal data converters...	744	18
Hand signal posters for download	735	28
Hand Signals Make All the Difference	735	26
JTDI vs CAPS	745	23
Pitot tubes, use covers but without heater	744	11
PQDRs now go through PDREP	744	12
Sheet metal stripped screw removal	744	16
Sling loading operations clarified (731-41)	737	22
AIRCRAFT GRD SPT EQUIPMENT (AGSE)		
AGPU--D/E model NSN update	740	23
DAWS--Conversion to 3-scale DAWS	741	23
Nitrogen generation and servicing equipment	744	13
Non-standard item TMs	735	25
PM AGSE help desk	741	61
Primer for CARC paint now aerosol	734	22
SATS--Unexpected movement permanent fix	736	24
AIRCRAFT LIFE SPT EQUIPMENT (ALSE)		
ASEK--Knife placement	736	20
MCU--Turn-in help	743	26
One-man life raft air hose fitting	742	60
SKRAM--Contents, number needed	735	24
AIRCRAFT TOOLS		
Sewing machine parts	736	61
Sheet metal stripped screw removal	744	16
AIRCRAFT, AH-64, APACHE		
Collective servocylinder bellcrank assy bracket	744	23
M230--Worm gear installation	739	22
M261--Contact, tube cleaning	745	25
Main rotor blade wedges demand	736	61
Unserviceable component list for turn-in	744	22
Water pooling after washing	741	26
AIRCRAFT, CH-47D/F, CHINOOK		
Aft rotor pylon step (ARPS) plans	738	22
Anti-collision light damaged by blades	737	23
M230--Barrel, remove for cleaning	738	26
Microclimate cooling system (MCS) parts	740	24
Work platform access door inspection	741	25
AIRCRAFT, OH-58D, KIOWA		
Blade tie-down wand assembly fix	739	25
Ground handling wheel pickup point	734	25
Ground handling wheel safety	741	24
Ground wheel NSN	737	60
M3P--Seating extractor	739	23
Mast-mounted sight servicing	739	24
Weapon systems cable connections	739	26
AIRCRAFT, UAV		
Shadow--TM & logbook, keep up-to-date	734	26
AIRCRAFT, UH-60, BLACK HAWK		
Electrical control panel replaces legacy parts	743	60
ESSS wing hookup electrical lead	742	61
Flight control computer turn-in	735	23
MEDEVAC portal, MilSuite access	735	21
Microclimate cooling system (MCS) parts	740	24
Shaft assy fan and drive needed for turn-in	737	24
Signal converters needed for turn-in	740	61
Static line anchoring device for parachuting	736	22
Transmission oil filter sleeve check	740	26
TS-3920C/ASM CTS calibration	742	60
Windshield wiper assembly	741	61
AMMUNITION		
AMMO Help website	743	60
Ammo placards for vehicles	745	42
ANTENNA, AS-1729, AS-1730		
Matching unit ground	742	48
AOAP		
LIW app, supplies	743	56
ARMORED COMBAT EARTHMOVER, M9		
Cutting edge, blade folding, hydraulics check	742	18
Ejector hydraulic cylinder rod, not a step	736	18
Hydraulic line clamp	736	19
Hydraulic line, fluid level check	743	19
Rear step, starter master relay, exhaust hose	735	18
ARMORED SECURITY VEHICLE, M1117		
Transmission pan filter, not a field-level fix	741	08
ARTILLERY EQUIPMENT		
DA Form 2408-4, who is responsible?	744	38
AVLB, M60/M48		
O-ring NSN change	735	04

Subject	Issue/Pg
AVLB, M104 WOLVERINE	
Battery retainer modification	741 06
Recuperator, reduction gear box leaks	740 02
AWARDS	
2013 DOD Maintenance Awards	738 61
2014 AAME nomination packets due soon	743 59
2014 CLEA awards announced	744 53
BACK COVER	
CLP vs LSA and LAW	737 62
Don't Let Ladders Be Your Downfall	744 62
First Line of Defense Against FOD Is You!	741 62
Job Isn't Finished Until Clean Up Is Done	742 62
Make PM a Priority Now	736 62
Santa Not Only One with Heavy Load	745 62
Save Your Sight...Use Combat Eyewear	739 62
Take Spare Barrels to the Field and Use Them	743 62
Take Time to Check for Loose Nuts	740 62
UTAP: One-Stop Shop for Training Material	738 62
Wake Up! Carbon Monoxide Dangers	734 62
BATTERY, HAWKER	
Tricking dead batteries back to life	742 12
BATTERY, LEAD-ACID	
Battery acid NSNs	741 61
Battery acid NSN	743 49
Battery box coating compound	745 61
Electrolyte NSNs	744 60
Solar charger info, NSN	738 10
VRLA--Charging, test equipment	734 12
BODY ARMOR	
Improved outer tactical vest PM	743 27
BRIDGE BOAT, TWIN-JET	
MK2--CPS code in parts TM	735 20
CABLES, COMMUNICATION	
Fiber optic cable PM	743 50
CAN, FUEL	
Water can differences	744 50
CAN, WATER	
Fuel can differences	744 50
CARBINE, M4-SERIES	
Be your own inspector	737 38
General PM tips	738 27
Improved cleaning kit components	740 36
M4 converting to M4A1	741 60
Rail bracket, grip NSN changes	738 44
Selector switch installed by 91F	744 41

Subject	Issue/Pg
CARRIER, AMMO, M992A2	
Cooling fan screens for maintenance	744 36
CARRIER, COMMAND POST, M1068-SERIES	
M1068A3--Hour meter location for APU	744 25
CARRIER, PERSONNEL, M113 FOV	
Battery maintenance	744 26
Hull rust prevention	738 04
Idler wheel lubing	743 06
Stowage seat kit	741 09
CBRN EQUIPMENT	
CBRN information resource center	737 44
Collective Protection Equip--HORN OFF button	734 42
JACKS for CBRN questions	743 44
JBPDS--Generator insulation, exhaust hose...	739 42
JCAD--M42 alarm needed	738 44
M41 PATS--Reagent grade alcohol only	740 41
M41 PATS--Shipping do's and don'ts	745 45
CLOTHING	
Army combat shirt ordering info	745 52
Barbed wire handler's gloves	738 60
Soutache braid stored in ACU pocket	739 60
Winter clothing articles	734 58
COMMERCIAL CONSTRUCTION EQUIP (CCE)	
Service kit NSNs	742 14
Tire tread direction, follow arrow	741 18
COMPACTOR, 815F	
Engine accessory belt with A/C NSN	741 60
Engine oil hot and cold check	745 19
COMPUTERS & SOFTWARE	
EMS-2--Sunsets with Windows XP	744 59
EMS NG--Newsletter available	741 59
EMS NG--Suspending troubleshooting	741 58
MSD software downloading	739 52
MSD-V3--Software upgrade needed	740 60
COMSEC EQUIPMENT	
CCI--Software upgrades online	738 45
Fill cable needed for connecting equipment	734 54
NET team training	742 51
CONTAINER HANDLER, RT (RTCH)	
Fuel/water separator draining	745 21
Starter, don't engage for more than 30 seconds	734 13
CONTINUITY	
Battle for PM	739 27
Dr. Drill Show	736 27
Forgotten Mission of NoSurprise	737 27
Hand Signals Make All the Difference	735 26

Subject	Issue/Pg
How the Vest Was Won, Part 1	741 27
How the Vest Was Won, Part 2	742 27
Knight to Castle 4	745 27
M1-series tank air induction system PM	744 27
PM Is Start of Beautiful Friendship (M16/M4)	738 27
PM Needs a Lot of Thought	740 27
Therapy for the Improved Outer Tactical Vest	743 27
CRANES	
Hand signal posters for download	735 28
Hand Signals Make All the Difference	735 26
DECON	
M12--Corrosion, heater, communications	740 42
EDITORIAL	
CSM Chance: Are You Ready for GCSS-A?	741 01
From GPS to PMCS	745 01
If TM Says Do It, Do It!	735 01
Key Point to Remember	744 01
Lose the Rabbit Habit	736 01
Maintenance Takes Time	743 01
Moment for Mechanics	734 01
PS: Free but Priceless	737 01
Report the Problem Gauge!	742 01
Study Warnings Ahead of Time	738 01
What Can You Do in 15 Minutes?	740 01
Your Best Insurance	739 01
EXCAVATOR, HYEX	
230--Starters, two types to choose from	742 21
230, 330--Fuel/water separator draining	745 20
Lubricity filter change interval	742 61
Warmup, cool down, engine oil and dipstick	738 20
FIRE SUPPORT VEHICLES	
M1200--Transmission pan filter, not field-level	741 08
FORKLIFTS	
6K--Battery retaining strap NSN	742 61
6K--Fuel shutoff solenoid for 165-hp engine	743 21
6K, ATLAS--Axle lubrication	734 18
6K, ATLAS--Fork extensions not allowed	739 61
6K, ATLAS--Fork extensions not allowed	743 20
ATLAS II--Starter NSN	744 60
Hand signal posters for download	735 28
Hand Signals Make All the Difference	735 26
FORMS, GENERAL	
DA Form 2404--Pencil vs ink	737 54
PDF fillable forms	738 60
FORMS, SUPPLY	
DA Form 1300-4--Make multiple copies	741 56

Subject	Issue/Pg
FORWARD REPAIR SYSTEM, M7	
Low coolant sensor, harness for Tier III engine	737 61
Retrofit free through 14 Jul 14	739 61
GENERATORS, SMALL	
3-kW, 5-kW--Engine oil, fuel, and heat PMCS	739 46
10-kW AMMPS--Overspeed shutdown fault	743 48
GRADERS	
130G--Exhaust pipe positioning for transport	741 18
130G--Hydraulic unloading valve use	742 20
130G--Turbocharger coupling leak fix	737 20
GRENADE LAUNCHER, M203	
Turn-in instructions	745 40
GUN, MACHINE	
M2A1--Barrel cover fits w/o flash suppressor	741 42
M2A1--Barrel, securing properly	742 42
M2A1--Barrel support removal tool nonexistent	741 43
M2A1--BFA installation different from M2	744 43
M2A1--LBS needed for boresighting	736 39
M2A1--M205 lightweight tripod available	742 43
M2A1--Sluggish firing cure	743 39
M3P--Seating extractor	739 23
M3P--Seating extractor correction (739-23)	744 61
M203 Tripod--Pinch hazard warning	735 38
M230--Barrel, remove for cleaning	738 26
M230--Cleaning, lubing, sideloader, hydraulics	737 25
M230--Worm gear installation	739 22
M240--DA 2028 submission for TM mistakes	738 43
M240C--Securing pin suggestion	738 05
M240H--Bipod assembly parts changes	739 36
M240H--Bipods available for free issue	743 60
M240L--M26 BFA for short barrel	741 36
M240L--M26 BFA for short barrel after MWO	743 43
M240L--Pistol grip, check for looseness	741 43
M240L--Safety spring, replace when removed	739 36
M240-Series--Ejection port cover reassembly	744 42
M240-Series--MWOs extended, renumbered	742 40
M240-Series--Op rod pin loose	739 44
M242--Barrel, only one now available	738 05
M249--AR vs LMG differences	743 40
M249--BFA differences	738 42
M249--Buttstock MWO	742 41
M249--Extractor kits with bad springs	743 60
M249--Extractor kits with bad springs	745 40
M249--Pistol grip changed	735 38
M249--Welded op rod, check for cracks	736 41
MK 19--COEI items missing from TM	737 41
MK 19--M205 lightweight tripod available	742 43

Subject	Issue/Pg
MK 19--Model differences	739 40
MK 19--Runaway, lower both charging handles	737 42
MK 19--Sear, feed slide SMR code changes	741 41
HARDWARE	
DILNet for hardware searches	739 53
Sealant for moisture seepage	736 60
Zipper lube NSN	740 61
HAZARDOUS MATERIALS & WASTE (HAZMAT)	
nPB limit in solvents changed	740 61
HEATER, PERSONNEL	
A-20--Control panel tips	737 05
HEATER, SPACE	
Convective--Battery pack recharging	741 50
HELMETS, AVIATION	
HGU-56/P--CEP disconnect, PM tips	743 25
HGU-56/P--Helmet sizes, NSNs	741 22
HELMETS, GROUND	
Night vision mount	744 47
HOWITZER, GENERAL	
TM 9-1000-202-14 sections for borescoping	736 40
HOWITZER, SP, M109-SERIES	
Cooling fan screens for maintenance	744 36
HOWITZER, SP, M109A6 PALADIN	
Bore evacuator O-ring swelling	736 02
Idler arm lubing	744 35
MCS exercise, water draining	741 05
HOWITZER, TOWED, M119-SERIES	
A3--APUBS vacuum release valve	737 06
A3--FCC touch screen cracking	741 03
Bore cleaning air tool kit	745 03
Wheel assembly upgraded with stem guard	742 08
HOWITZER, TOWED, M777A2	
Belly pan quick-release pin lubing	740 07
Breech pivot pin/roller lubing	740 08
DFCS CLE cable pinching	737 07
Website for manuals, training, software, etc.	736 03
INTERNET	
Army Enterprise Service Desk (AESD)	738 57
milSuite websites	739 54
Portals, forums may not be official	738 58
KITCHEN EQUIPMENT	
MBU--Dust prevention	736 48
MBU--Pack extra filters for deployment	734 61
MBU--V3 upgrade for adjustable heat output	736 46
MTRCS--Hook arm pin damage	745 48

Subject	Issue/Pg
XCK2000/E1--Crank handle NSN	737 60
LASER RANGEFINDER	
AN/PED-5--Input/output (I/O) cable damage	741 39
LAUNDRY ADVANCED SYSTEM (LADS)	
Doors closed to keep out dirt, dust	737 51
Drain water before cold weather hits	744 48
LOADER, BACKHOE (BHL)	
HMEE-1--BII/COEI charts updated	741 20
HMEE-1--Warm-up/cool-down, battery switch...	740 18
Roof pad NSN correction (729-21)	739 60
Secondary air filter NSN	742 60
UTAP maintenance video	742 60
LOADER, SCOOP-TYPE	
966H--Battery disconnect, hood tilt, engine oil...	734 14
966H--Bucket lubing	736 16
H100C--Alternator NSNs	737 21
MW24C--Rotary dimmer switch NSN	734 19
LOADER, SKID-STEER, BOBCAT	
M400T/W--Door assembly NSN	739 60
M400W--Solid rubber tire NSNs	734 20
M400W--Solid tire NSN	734 19
LOGISTICS ASSISTANCE	
SAMS-E help desk support	734 61
TACOM LAR, how to find	734 48
LOGISTICS MANAGEMENT	
EPIC policy search tool	744 56
GCSS-Army data cleanup	743 53
GCSS-Army EXORD 001-14 released	734 60
GCSS-Army glossary	742 61
GCSS-Army SASMO training	734 60
GCSS-Army training, milSuite forums	736 57
GCSS-Army Wave 2 transition prep	744 58
GCSS-Army website reminder	745 61
GCSS-Army worldwide program update	737 60
LIW training	738 54
SAMS-E developer on milSuite	740 61
SAMS-E info on AKO	736 61
WebFLIS	736 56
MAINTENANCE MANAGEMENT	
10% variance on maintenance services	736 52
COEI, BII, AAL turn-in requirements	739 56
Deferred maintenance tracking	740 58
Manufactured tool limits	742 56
Shop stock, when allowed	737 55
MAINTENANCE, GENERAL	
FMSWeb	740 22

Subject	Issue/Pg
LOGSA maintenance/readiness mailboxes	738 61
Oshkosh equipment warranty claims	744 60
MASK, PROTECTIVE	
M40, M42--Be Your Own Inspector	742 44
M40, M42--Fitting solutions	745 44
M40-Series--M40 can't covert to M40A1	741 35
M52--Nose cup flap sticking	740 44
MINE CLEARING EQUIPMENT	
Husky--Cab ledge step, detection heads	736 15
Husky--Dust cap, air filter cleaning	738 18
Husky--Fuel/water separator draining	736 14
Husky--Shock absorber bracket loose	736 12
Husky III--CTIS control unit NSN	741 60
MISSILE, AVENGER	
Contact, non-skid strips, no step, climbing...	736 42
Primary power unit PM tips	737 35
W87 cable, canopy, azimuth brake, FLIR...	737 36
MISSILE, HIMARS	
Biannual/biennial definition (734-46)	742 46
Cab spanner nuts, cab lock, wash rack, batteries	745 36
Shock absorber mandatory replacement parts	734 46
MISSILE, PATRIOT	
AMG--Feed horn plugs, pneumatic pump covers	734 43
Filters, GPS cable, DLTM doors, antenna puller...	734 44
SSS--Keypad temp, straps for travel	739 35
MISSILES, GENERAL	
PQDRs now go through PDREP	744 12
MLRS	
Cab, launcher safety	742 06
Dash lights, hoist carriage assy, prop shaft bolts...	742 36
Desiccant panels, cable security, limit switches...	743 36
Heater cleaning, fuse replacement	743 03
Water cleaning precautions	737 02
MORTARS	
DA Form 2408-4, who is responsible?	744 38
M120, M121--Store legs before travel	734 42
M120, M121--Store legs correction (734-42)	741 39
M224/A1--Handle, firing mechanism torque	741 38
Paint only for alignment lines	737 40
Sight protection during baseplate settling	745 41
TM 9-1000-202-14 sections for borescoping	736 40
MOUNT, WEAPONS	
M66--Parts info	738 41
M153 CROWS II--Components remain	736 41
M153 CROWS II--Travel locks	739 45

Subject	Issue/Pg
NIGHT VISION EQUIPMENT	
AN/PVS-6, -7, -14--Image intensifier tube	740 46
AN/PVS-7B, -7D, -14--Batteries, caps, data label	745 50
AN/PVS-14--Helmet mount hardware change	738 50
AN/PVS-14--Retaining ring loose	741 40
Helmet mount, order the latest	744 47
PISTOLS	
M9--Holster NSNs	736 38
M9--Holsters, new NSNs added	742 39
POL	
PS MAGAZINE	
Back issue requests	736 59
How to order	734 50
Issues too large to email	738 61
PS: Free but Priceless	737 01
Radionerds website for back issues	742 61
Search engine instructions	741 53
Unit-maintained equipment covered by PS	737 59
Winter clothing articles	734 58
PUBLICATIONS	
AR 750-1 released	734 49
AR 750-10 revised	736 55
AR 750-43 revised	742 57
AR 750-59 revised	741 61
Aviation FMs being converted to TMs	737 61
Bring pubs back from deployment	738 51
DA Pam 25-30 for pubs availability	742 61
DA Pam 385-1 revised	736 59
DA Pam 385-11 released	736 59
DA Pam 385-63 revised	741 60
DA Pam 738-751 revised	742 23
DA Pam 750-1 revision adds CMDP	738 57
DA Pam 750-3 revised	738 57
DA Pam 750-43 revised	739 61
EMS NG viewer printing	742 53
EOPDB for pubs list	734 47
FM 3-20.21 helps with Bradley gunnery	743 05
Official manuals only for maintenance	737 52
Ordering Army publications	734 50
Publications status tracker	744 61
Winter publications	734 58
RADIO SET, SINCGARS	
Radio frequency cable damage	737 46
REELING EQUIPMENT	
MARS reels lighter, stronger	738 46
RIFLE, M16-SERIES	
Be your own inspector	737 38

Subject	Issue/Pg
General PM tips	738 27
Improved cleaning kit components	740 36
Rail bracket, grip NSN changes	738 44
Selector switch installed by 91F	744 41
Sight post, square vs. round	739 41
RIFLE, SNIPER	
M107--XM107 conversion info	737 42
M107--XM107 now converted	734 60
M110 SASS--Bolt repair part NSNs	745 38
M110 SASS--Day sight dust covers	739 39
M110 SASS--Trigger assembly POC	737 42
M110 SASS--Trigger assembly replaced?	734 60
M2010--Components for turn-in with rifle	739 38
ROBOTS, GROUND	
310 SUGV Mini-EOD--Weight, track check	740 20
EOD robot parts ordering system	744 60
XM1216 SUGV--Power button warning	734 21
ROCKET LAUNCHER	
M260, M261--Cleaning, PMCS, loading tool...	734 40
SAFETY	
Fire prevention	737 56
Hand signal posters for download	735 28
Hand Signals Make All the Difference	735 26
Heat injury prevention, Part 1	740 50
Heat injury prevention, Part 2	741 46
MSDS at DLA's HMIRS website	737 61
SCRAPER, EARTHMOVER, 621B	
Guide roller lubing	736 17
Starter NSN	745 61
SIGHTS & SCOPES	
AN/PSQ-23/A--Heater, turn off	734 39
Batteries no longer included with new items	744 44
M151--Night vision goggle addition	745 39
SLEEPING BAG	
Replacement parts, NSNs	737 48
SMALL ARMS	
Armorer no longer weapons maintainer	738 43
Bubble wrap no good for long trips	740 35
CCMCK gage needs no calibration	743 42
Clearing rod, how to make	734 38
CLP vs LSA and LAW	737 62
COMET: TMs, tool protection, jack stands...	736 35
DA 2407-E, bolts, barrels, transport, CCMCK...	738 38
Lubes and weapons they're used on	741 44
Packing for safe travel	734 36
PQDR submission website	734 35
Safety wire, one loop or more?	739 39

Subject	Issue/Pg
SUPPLY, GENERAL	
Accounting for nonexpendible COEI	742 58
Component protection in storage	740 52
Estimated ship date tools on LIW	739 58
FED LOG help for ordering parts	738 52
PBUSE AIT quick setup guides	743 54
Shelf-life information	745 54
Supply discrepancy reports	745 58
WebFLIS changes coming	738 60
SURVEILLANCE SYSTEMS	
BETSS-C--Generator PM	739 46
TANK, M1-SERIES	
Air induction system PM	744 27
Battery retainer modification	741 06
Breech crank assembly bolts missing	745 07
Breech inspection, cleaning, servicing	734 04
Bustle rack cargo net, extension	735 02
Cleaning inside and outside of tank	738 08
DA Form 2408-4, who is responsible?	744 38
DSESTS--M934 truck still prime mover	734 06
Gun card, keep updated	737 04
M1A1--M19 particulate filter replacement	734 05
M18A1 filter canister caution	742 07
Recuperator, reduction gear box leaks	740 02
Replenisher level, recoil system bleeding	745 08
Transmission oil filler neck needs funnel	743 07
Turret lifting device bolts, mount assembly	739 08
Turret screens not for hanging gear	739 07
TENTS	
Zipper lube NSN	740 61
TEST EQUIPMENT	
DSESTS--M934 truck still prime mover	734 06
MSD software downloading	739 52
STE-M1/FVS--Bradleys with ED	742 60
TS-3920C/ASM CTS calibration	742 60
TIRES	
CCE tire tread direction, follow arrow	741 18
DOT code determines shelf life	735 12
General PM	740 14
Retreads not allowed on some vehicles	738 14
Safety tips	738 12
Tire chain use, NSNs	734 07
TOOLS	
Accountability checklist	740 38
Common #1, #2 replaced by SATS?	745 43
SATS--Corrosion, generator door, travel prep...	738 35
SATS--Door handle NSN change	739 60

Subject	Issue/Pg
SATS--Tool drawer layout	742 46
Torque wrench, zero out to maintain accuracy	745 43
TRACTOR, D7E/F/G/R	
Rear winch cable fix	737 18
TRAILERS	
Brake air coupling identification	739 21
M1076--Interface kit components explained	745 12
M1077--Stowage box repair, replacement	735 08
M1101, M1102--Adjustable lunette	738 17
M1112--Hand brake repair parts NSNs	741 14
M1112--Hand brake repair correction (741-14)	743 61
TRAILERS, SEMI	
Linseed oil to protect wood decks	740 19
M129A3/A4--Data plate model identification	741 16
M870/A1--Wood decking replacment	735 09
M870/A1--Wood deck correction (735-9)	743 61
M870A1--Wood decking kit	740 19
M872A4--Bumper pin NSN replacement	741 60
M969A3--Radar fuel level sensor NSN	738 61
M1000--Ramp chain restraint snap hook	743 17
TRAINING	
Driver's check ride explanation	739 57
LIW training	738 54
NET team training	742 51
SASMO DCO training session	737 60
Transportation basic freight traffic course	736 58
UTAP for recovery vehicle info	734 15
UTAP newsletter covers legacy equipment	742 60
UTAP: One-Stop Shop for Training Material	738 62
TRANSPORTATION	
Basic freight traffic course	736 58
CDDP launched	738 56
TRUCK, M915-SERIES	
M916A3--Gladhand/plug holder NSN	738 60
M917A1--Air dryer NSN	738 60
Tire size differences	743 16
TRUCK, M1070 HET	
A0/A1--Wheel hub assembly seal	739 60
Heated LED headlight NSN	736 60
Transfer case rotary pump NSN	744 60
TRUCK, 1 1/4-TON, HMMWV	
Cdr's seat, don't remove bolts to recline	744 05
Door latch lubing	738 12
Frag armor, OGPK repair parts	745 14
Fuel solenoid flyback diode	744 04
Geared hub fill plug washer	738 61
Hardtop cover NSNs	741 10

Subject	Issue/Pg
LED headlight NSN	737 61
LED headlight NSN	741 61
M1151--Tarp for gunner's turret	737 17
Self-locking nut NSN change	741 60
Snow plow kit	744 03
Up-armored--Door NMC criteria updated	736 06
Up-armored--Windshield deicer shorting	736 04
TRUCK, 5-TON, M939-SERIES	
M939/A1/A2-Series--Starter assembly NSN	745 61
M939A2-Series--Alternator change for Hawkers	743 15
TRUCK, FMTV	
Batteries, don't mix Hawkers with wet cell	744 06
Battery tray retainer missing corrosion coating	742 11
Bogie O-ring NSN	736 60
Brake air tanks, drain after operation	735 06
Brake spider NSN	739 60
Cab support tool use, NSN	735 05
Cargo cover kits, components	739 10
Cargo cover repair	741 12
GRS for soft shell cabs	744 09
Interconnecting box NSN change	737 60
LTAS--CTIS switch bypass cable unplugged	745 11
LTAS--M66 ring mount parts	740 10
LTAS -A1P2--Auxiliary starter relay bracket	744 08
LTAS -A1P2--Cab door damper NSN	745
M1081--Cargo bed D-rings, clean and lube	738 15
M1083--Tailgate bumper damage	744 07
M1083/A1P2--M66 mounting instructions	744 09
M1083A1P2--Passenger-side door window	737 60
M1089A1--Wrecker load test faults	735 07
Oil pressure gauge check	736 10
Safety mirrors	735 08
TRUCK, HEMTT	
A4 Models--Hydraulic enable switch to OFF	737 14
A4 Models--Hydraulic filter O-rings	737 14
A4 Models--Steering gear replaced	738 16
A4 Models--Temperature sensor O-rings	736 61
A4 Models--Universal service kit NSN	734 60
A4 Models--Wiring harnesses over manifold	737 15
Heated LED headlight NSN	736 60
LED headlight NSN	744 60
M978A4--Hydraulic pump assembly warranty	737 16
M978A4--V1 emergency valve MC bracket	745 15
M1120A2/A4--E-CHU/CHU removal	734 61
Multiple use adapter (MUA) usage	736 08
Spin-on oil filter conversion	736 61
TRUCK, PALLETIZED LOADING (PLS)	
A1 Models--Hydraulic enable switch to OFF	737 14

Subject	Issue/Pg
Basic first aid kit, item expiration dates	739 61
Heated LED headlight NSN	736 60
M1074, M1075--4500SP TCM NSN	741 60
M1074, M1075--Air intake hose NSN	734 61
M1074, M1075--Mud flap hanger fix	743 14
M1074, M1075--Speed sensor for 24V system	745 14
M1074, M1075--Transmission fluid types	743 13
M1074A1, M1075A1--Hydraulic hose 2-piece	743 14
M1074A1, M1075A1--Shift cable boot	740 12
M1074A1, M1075A1--Warning light, MG mount	734 61
M1075/A1--E-CHU/CHU removal	734 61
Mud flap hanger kit	737 61
TRUCKS, GENERAL	
Battery box coating compound	745 61
Elastic cord for canvas covers	738 60
GPK, OGPK maintenance TMs	734 37
GRS guidance, PMCS, NSNs, deadlining...	737 10
Hand signal posters for download	735 28
Hand Signals Make All the Difference	735 26
Operator's manual, keep with vehicle	740 09
Parts bin helps with maintenance organization	743 11
Retreads not allowed on some vehicles	738 14
Service kit NSNs	742 14
Solar charger info, NSN	738 10
Tire chain placement for tactical vehicles	734 10
Tire chain use, NSNs	734 07
Tire safety tips	738 12
Towing safety	735 10
Towing safety update (735-10)	741 17
VEHICLE, FIGHTING, M2/M3 BRADLEY	
Battery charging, CIV tarp, gun card	734 02
DA Form 2408-4, who is responsible?	744 38
FM 3-20.21 pre-fire checklist	743 05
FSS test set upgraded, renamed	738 06
Idler wheel nuts loosen	742 03
M240C--Securing pin suggestion	738 05
M242--Barrel, only one now available	738 05
M242--Cleaning, lubing, assembly, PMCS...	745 04
M242, TOW--Firing PM	742 04
Schematics for troubleshooting	743 05
STE-M1/FVS not needed with ED	742 60
Track connecting with tanker's bar	744 37
VEHICLE, MRAP	
Driver's survey	743 12
Driver training, publications	745 16
M-ATV--Brake chamber vent line replacement	740 13
M-ATV--Cushion set	736 60
M-ATV--Lube order update	743 61
MaxxPro--AFES battery backup kit	743 60
MaxxPro Dash/DXM--Air filler valve NSN	743 60
MEL TB available	736 60
VEHICLE, RECOVERY, M88-SERIES	
A1--Personnel access door lubing	738 07
End connector, center guide torque	737 08
Spare roadwheel rust prevention	741 02
VEHICLE, STRYKER	
AFES PMCS checks	739 02
DA Form 2408-4, who is responsible?	744 38
Hub fill plug O-rings	735 03
IETM contributions requested	740 04
Left window extraction kit (LWEK)	740 05
M1128 MGS--Battery box boots, cover	741 04
M1129A1, XM1252--Mortar tube stress cracks	743 09
M1135 NBCRV--ACADA water problem	736 44
M1135 NBCRV--Moisture, fluids, axle oil	737 43
M1135 NBCRV--SSA troubleshooting	743 46
Recovery rope improved	738 02
Run-flat tire tips	739 04
Storage of gear and equipment	739 06
Winch pulley lubing	743 08
VEHICLES, COMBAT	
Air filter ice, moisture damage	743 04
Battery box coating compound	745 61
Hand signal posters for download	735 28
Hand Signals Make All the Difference	735 26
Operator's manual, keep with vehicle	740 09
Service kit NSNs	742 14
Slat armor not for storage	739 05
Towing safety	735 10
Track pad identification	737 09
VEHICLES, GENERAL	
Hand signal posters for download	735 28
Hand Signals Make All the Difference	735 26
Operator's manual, keep with vehicle	740 09
WARRANTY	
Oshkosh equipment warranty claims	744 60
WATER PURIFICATION	
TWPS--Filter NSNs	734 16
WATER PURIFICATION UNITS (ROWPU)	
Filter NSNs	734 16
WATER SUPPLY	
Dehydration dangers in winter	734 56
FAWPSS--Cargo container NSN	744 60
Water publications	736 50