



### Solid Film Lubricant

The NSN for solid film lubricant listed on Page 37 in PS 564 (Nov 99) is no longer valid. Use NSN 9150-01-260-2534 to order SFL.

### HMMWV Parking Brake Cable

NSN 2590-01-265-3185 gets the left-hand parking brake cable shown as Item 3 in Fig 130 of TM 9-2320-280-242-1. The NSN shown in the TM gets the wrong cable.

### Keep AN/PSS-12 Close to Ground

Sweep with the AN/PSS-12 mine detecting set as close to the ground as possible—the closer the better. Page 22 in PS 565 (Dec 99) said to sweep with the search head 6 inches above the ground over uneven ground. DON'T DO IT. That's wrong. Never sweep more than 2 inches above the ground, regardless of how rocky the ground is. Sweep slowly, with the head as close to the ground as you can get it. Carefully follow the instructions in TM 5-6665-298-10.

### HMMWV Safety Message

Right now, check all HMMWV power distribution boxes, NSN 6110-01-446-7126, for a label that says "VER 14.0A". VER 14.0A boxes won't let the engine start on its own after the truck has been shut down. Replace all boxes that *DO NOT* have this label with new boxes, per TACOM safety-of-use message (SOU) 00-006 (24 Nov 99). Boxes that don't have the label can be turned in for full credit until Jun 00. See the SOUM for details.

### Better M157 Cap

If you have trouble unscrewing the fog oil tank cap on the M157A2 smoke generator, order the new cap, NSN 2590-00-459-8477. The new cap has metal tabs that make it easier to grip.

### 15-KW, 30-KW Fan Belts

Having trouble getting the right fan belt for your 15-KW and 30-KW tactical quiet generators? Get the fan belt for the 15-KW, Item 53 of Fig 12 in TM 9-6115-643-24P, with NSN 3030-01-463-9774.

The fan belt for the 30-KW, Item 61 of Fig 12 in TM 9-6115-644-24P, is NSN 3030-00-528-4626.

DISTRIBUTION To be distributed in accordance with the initial distribution number; DMI 343312 requirements for T8-43 PS Series.

**Would You Stake Your Life *right now* on the Condition of Your Equipment?**