

New Deal for No Seal


WHAT A LOUSY DEAL! I'M TELLIN' YA THAT A LEAK IN MY ENGINE ACCESS PANEL SEAL IS OK! HONEST!



Operators, the -10 TMs are wrong when they say your M113-series vehicle is NMC if the engine compartment access panels won't seal.

TACOM says your vehicle is good to go even with a **leaky** seal. The engine fantower keeps any dangerous exhaust from entering the troop compartment.

Make a note until the TMs can be updated.



Fantower keeps fumes out of troop compartment

Armored Vehicle-Launched Bridge . . .

Do You Smell Gas?

Loose or missing access covers between the crew and engine compartments of the armored vehicle-launched bridge are downright dangerous.

Loose or missing covers can:

- ⑦ Let exhaust gases seep into the crew compartment. Carbon monoxide in the gases can kill you!
- ⑦ Let an engine fire spread into the crew compartment before you have a chance to get out.

Check the access covers right now. If they're loose or missing, get your mechanic to tighten or replace 'em right away.

Mechanics, replace any damaged or missing gaskets, too.

Keep access covers in place

