



### HMMWV 2-Man Camo Curtain

A sharp reader noted that we left the 2-man crew curtain assembly out of the listing of woodland camouflage covers and doors for HMMWVs on Page 5 of PS 575 (Oct 00). Get the assembly with NSN 2540-01-450-4018.

### Getting Pure Argon

The Army has had trouble controlling the purity of the argon gas used with Stinger missile systems so it's going to single-source supply. Argon not 99.998 percent pure hurts the Stinger's cryogenics and causes self- test faults. Units now must order 100 percent argon, NSN 9135-00-882-1793, directly from Kelly Air Force Base, TX. For ordering info, contact Elena Barron at (210) 925-4844, DSN 945-4844, fax - 8048, or e-mail: [elena.barron@kelly.af.mil](mailto:elena.barron@kelly.af.mil).

### Battery Post Washers 5986

Mechanics, you can help prevent corrosion from forming on all lead-acid batteries by adding a felt washer to battery posts before installing the cable clamps. The washer absorbs moisture and keeps the post clean and dry. NSN 5970-01-101-4147 brings 100 felt washers.

### Collimator Lamp 5324

Need a replacement lamp for the collimator, NSN 1240-00-757-3291, on your weapon system's azimuth test fixture, NSN 4931-00-769-1596? You won't find the NSN in any parts manual. Get the lamp with NSN 6240-00-617-1713.

### M40/M42 Mask Repair Kits 5955

Some M40/M42-series masks have loose or separated nosecup valve seats, which fog the eyelenses. A repair kit is available for NBC NCOs to fix bad valve seats. To get the kit, fax SBCCOM's Sam Carter at (410) 436-6533, DSN 584-2149, or fax -2149. E-mail him at [samuel.carter@sbccom.apgea.army.mil](mailto:samuel.carter@sbccom.apgea.army.mil). He needs your name, shipping address, phone number, and the number of valve seats needed.

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

**Would You Stake Your Life *right now* on the Condition of Your Equipment?**