


CH-47 series...

The M130 Cover-Up



Crew chiefs, you've probably noticed that the cover for your M130 general purpose dispenser has a cover-up problem, on CH-47 aircraft. The cover, NSN 1560-01-271-6463 doesn't protect the dispenser because it's mounted and used exclusively in the flare mode.

That's because the dispenser has two holes not covered by the cover. So the holes funnel rain, melting snow, sand, and debris into the dispenser. That soon corrodes the firing contacts and makes the dispenser NMC.

So get a nylon cover that protects the dispenser in all weather and in both modes with NSN 1730-01-456-2557.

Hold On to FM 1-202

Aviators, on page 37 of PS 575 we told you that FM 1-202, *Environmental Flight*, was being replaced by FM 1-201, *Fundamentals of Flight*. Well, it is, but the publication of the new pub has been delayed. Hold on to your old pubs until FM 1-201 hits the field.