



On-line Weapons Training

Training on the M2, MK 19, and M249 machine guns is now available on-line at <http://aeps.ria.army.mil/aepsbpublic.cfm>. You will need to have a login and password or fill out an access form to use the site. Then click on TRAINING.

M2 CLEARANCE CHANGED

Armorer's, the standard for the clearance between the M2 machine gun's cover latch and the receiver's top plate has been changed to .02 inch, regardless of whether your unit is CONUS or OCONUS. The check is in Para 3-3 in TM 9-1005-213-23.

HELMET TROUBLESHOOTING

Having problems communicating while wearing the HGU-56/P or the SPH-4B flight helmets? There is an additional electronic test set, NSN 6625-01-251-8705 that units can buy to troubleshoot the commo parts of their helmets. The set costs about \$335.00.

CABLE TUG OF WAR Update

Get the UG-1366/U RF connector needed to extend the radio cable on your CH-47D with NSN 5935-00-177-2712. Page 37 of PS 588 has the wrong NSN.

SOM for Aircraft Update

On Page 2 in PS 589 we said that information on aircraft safety-of-use messages is covered in AR 95-3 Aviation: *General Provisions, Training, Standardization and Resource Management*. The reference should be AR 95-1, Flight Regulations. All the information contained in AR 95-3 was moved into AR 95-1.

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

Would You Stake Your Life ^{right now} on
the Condition of Your Equipment?