

Connie's
☆ POST
☆ SCRIPTS



WHO SAID
THIS WAS
A SHORT-
CUT?

SB 700-20 APPENDIX H UPDATE

Note that Appendix H of SB 700-20 now authorizes/substitutes LIN combinations of machine gun mounts. The combinations are M12647 (authorized) and M74823 (substitute) and M11071 (authorized) and M74618 (substitute). The changes were applied to SB 700-20's master file in Mar 02. The official pub date of the new appendix is 1 Jun 02.

FMTV HYDRAULIC FLUID

You can also use Royco 756 hydraulic fluid in the air/hydraulic manifold on FMTVs. It joins MIL-H-5606 as the only approved fluids for this application. Royco 756 can be mixed with MIL-H-5606 in the same manifold without causing performance problems. Royco 756 is available in these sizes:

- NSN 9150-00-224-4134 (quart)
- NSN 9150-00-252-6383 (gallon)
- NSN 9150-00-265-9408 (55-gal drum)

AOAP on the Web

Having trouble finding the Army Oil Analysis Program Management Office? Check out these links:

<http://www.logsa.army.mil/prodserv.htm>

<http://www.logsa.army.mil/alc/index.htm>

<http://weblog.logsa.army.mil/aoap/openpg.htm>

You can find out about AOAP, and check out what equipment is enrolled and their sampling intervals.

Drive to Arrive

Soldiers often forget the basics of safe driving when they park their trucks and tanks and fire up their POVs. Every 72 hours, a soldier is killed in a POV accident. Help prevent accidents by showing star-studded country music video clips as part of unit safety briefings. Download from the Safety Center web site at <http://safety.army.mil>. Also check out the POV Risk Management Toolbox for tips and tools to help in the Army's "Drive to Arrive" accident prevention campaign.

BATTERY CHARGER CHANGE

The PP-34/MSM, lead acid battery charger, NSN 6130-00-224-6089, is obsolete. Order the PP-1660E, NSN 6130-01-446-4132, instead.

250 CFM COMPRESSOR FILTER

NSN 2940-01-186-0592 gets the oil filter element shown as Item 9 in Fig 74 of TM 5-4310-452-24P. The NSN listed in the TM gets the wrong filter.

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

Would You Stake Your Life *right now* on
the Condition of Your Equipment?