

LOOK AT FIRE EXTINGUISHER VALVE



Crews, check the valve on the 5-lb fixed fire extinguisher assembly in the crew compartment of your M104 Wolverine. If the valve has one of these three serial numbers—1092, 1208, or 1212—get the extinguisher replaced now!

The Santa Barbara Dual Spectrum valves originally used on these fire extinguishers were defective. Tests showed that the valves stopped working after several automatic discharges and could then only be discharged manually.

All of the defective valves have been replaced except for three. Serial numbers **1092, 1208** and **1212** are still missing in action.

Do you have one of these valves on the fire extinguisher in your Wolverine?

Take a close look at the serial number on the fire extinguisher valve. If you find one of the missing serial numbers, contact your local TACOM LAR or the Wolverine program manager's office (DSN 786-5522/5557 or (586) 574-5522/5557) for turn-in information.

		DUAL SPECTRUM®			
SENSING AND SUPPRESSION SYSTEMS					
FIRE EXTINGUISHER VALVE					
P/N	283281-0002	MFG	61423	S/N	1092
CUSTOMER P/N	19207 ASSY - 12324276				
SERVICE	HALON 1301 & N2		OPER PRESS.	750	PSI
CONT NSN			SBD5 CAGE 05BU0 U.S. PAT. NO. 4,579,315		
SANTA BARBARA DUAL SPECTRUM 163 AERO CAMINO GOLETA, CALIFORNIA 93117					