

# A Plug for Plug ID




Dear Editor,

The troubleshooting procedures for the Paladin's charging system require removing the cannon plugs for the fuel pump generator system relay and the blower motor relay.

Both cannon plugs look the same, so it's easy to accidentally mix up the plugs when reconnecting them to the relays. If you do that, the system won't charge at all and you've just compounded your original charging problem.

We've stopped the mixup by painting a small white mark on one cannon plug and relay. The next time both have to be unplugged, it's obvious which plug goes to which relay.

Motor Pool  
3/18 FA  
Ft Sill, OK



From the desk  
of the *Editor*



You've plugged up that potential problem. Thanks!