


GETTING THE M24 REPAIRED



Since the M24 sniper weapon system must go to Remington Arms for most repairs, it has to be handled differently than the other weapons in the arms room.

To get an M24 repaired, ask your installation accountable property officer to prepare a DD Form 1348 using a document identifier code (DIC) FTE (report of excess) and AOE (requisition with exception data), which are covered by Chapter 7 of AR 725-50, *Requisition, Receipt, and Issue System*.

The exception data should include the M24's serial number, the FTE document number, and a point of contact, including a commercial or DSN phone number.

TACOM-Rock Island will respond with an FTR (reply to report of excess) that will direct you to ship the M24 to Remington. Remington will return the repaired weapon to you using the document number from the AOE.

If you're OCONUS and don't have access to US registered mail, TACOM-RI will direct you to send the M24 to Anniston Army Depot, which will ship it to Remington.

The FTE and AOE can be phoned into TACOM-RI at (309) 782-2774/DSN 793-2774 or faxed to (309) 782-2640/DSN 793-2640 or e-mailed to bynumj@ria.army.mil

For more information, contact George Riley, (309) 782-3843/DSN 793-3843, or Doug Carlstrom, (309) 782-2361/DSN 793-2361, or your local TACOM-RI logistics assistance representative.