

# DISPENSING DISPERSER INFO

THIS M37 IS STARTING TO WEAR OUT! WHERE ARE WE GOING TO GET REPAIR PARTS FOR THIS?

I DON'T KNOW! I DON'T EVEN HAVE A TM FOR IT.



THE ARMY IS FIELDING THE M37 RIOT CONTROL AGENT DISPERSER, NSN 1040-01-463-0157, TO MP UNITS AND THE GUARD AND RESERVES.

IF YOUR UNIT RECEIVES THE M37, HERE ARE A FEW THINGS TO REMEMBER.

- The M37 is covered by TM 3-1040-287-12&P. You should have received a copy with each M37. If you didn't, have your pubs clerk order more.
- You should also have received refill and repair kits for every 2 or 3 M37s. The repair kit has no overall NSN, but you can order its components with the NSNs in the Repair Parts and Special Tools List in the TM.
- All M37s are under warranty through April 2004. See Page 0001 00-2 in the TM for more info.

THE REFILL KIT IS MADE UP OF THESE ITEMS...



- Screw cap bottle, NSN 6640-00-688-7881
- Funnel, NSN 6640-00-063-7872
- Antiseizing tape, NSN 8030-00-889-3534
- An alternative to the M254 service kit transfer tube for filling the transfer bottle is a pour spout, NSN 7240-00-782-3501, which is being added to the refill kit.