

FILTER SLEEVE REMOVAL REVISITED

THIS NEW TOOL DOESN'T QUITE FIT ON THE OIL FILTER SLEEVE.

THIS ONE SHOULD DO THE TRICK!



OOPS, we goofed! On Page 37 of PS 596 (Jul 02), the drawing measurements to make the positioner tool are off.

The diagram did not show that the critical distance between the two pin bolts is 5 inches from the outside of the first bolt, across the center of the tool to the outside of the second bolt.

With the previous instructions the positioner tool won't fit properly, and you'll have to grind off about .030 inches from each bolt on the outside edge to make the tool fit.

HERE'S A CORRECTED DIAGRAM TO MAKE THE TOOL. MAKE A NOTE UNTIL THE TM IS UPDATED.

