


# TURN IN PARTS FOR REPAIR



ARE YOU FINISHED TESTING MY LRUS ON THE BSTF YET?

NOT YET.

I'VE GOTTA TOSS THESE BAD CARDS AND GET SOME NEW ONES.


HOLD ON, SOLDIER! ALWAYS TURN IN BAD CIRCUIT CARDS AND POWER SUPPLIES FOR REPAIR.

Are you mechanics and supply types having problems getting replacement circuit cards for the AN/TSM-191(V)3 base shop test facility (BSTF)? You can help by turning in failed circuit cards and power supplies for repair.

The BSTF, which supports the MLRS, Avenger and especially the Kiowa Warrior, is experiencing high component failure because of poor handling and damage to circuit cards and power supplies.

Some units just replace the cards and power supplies, but don't turn in the broken items for repair and reuse. That creates a shortage in the supply system.

Without cards and power supplies, the BSTF will not be able to test and isolate faults in weapon system line replaceable units (LRUs) and shop replaceable units (SRUs). That will hurt unit readiness and mission performance.



I'M A FAILURE! BUT IT WASN'T MY FAULT...

I COULDN'T GET THE CARDS AND POWER SUPPLIES I NEEDED TO DO THE JOB RIGHT!

I HEAR YA!

IF YOU HAVE ANY OF THE FOLLOWING CIRCUIT CARDS AND POWER SUPPLIES LYING AROUND THE MAINTENANCE SHOP, TURN 'EM IN.




1. Low voltage DWG card, NSN 5998-01-413-8422.
2. Mirco-processor card, NSN 6625-01-450-5880.
3. +/-15 power supply, NSN 6625-01-451-3465
4. +/-55 power supply, NSN 6130-01-388-5632.

For turn-in instructions, contact AMCOM's Kevin Williams, weapon system coordinator at DSN 746-3564, (256) 876-3564, or email: [kevin.williams@redstone.army.mil](mailto:kevin.williams@redstone.army.mil)

Or contact Mattie Shaneyfelt at DSN 746-9551, (256) 876-9551 or email: [mattie.shaneyfelt@redstone.army.mil](mailto:mattie.shaneyfelt@redstone.army.mil)

or Cathy Robbins, at DSN 897-5741, (256) 313-5741 or email: [cathy.robbs@redstone.army.mil](mailto:cathy.robbs@redstone.army.mil)