

ALSE...

Life Preserver UPDATE



YES, THE 120-DAY LPU LEAK TEST INSPECTION INFO WE HAD ON PAGE 41 OF PS 596 (JULY 02) IS **GOOD**.

THAT INFO TOLD YOU TO MAKE SURE THE GASKET IN THE CO₂ CARTRIDGE IS GOOD EVERY 120 DAYS.



The multi-service Air Force T.O. 14S-1-102, which has Army TM 5-4220-202-14 assigned to it, has changes that have not been included in the Army TM. TM 5-4220-202-14 has only been updated through Change 15.

For all the Air Force, however, the T.O. is up to Change 24, which now says to inspect life preservers once a year, not every 120 days as stated in the Army TM.

Until the latest Air Force changes are coordinated with the Army and incorporated into TM 5-4220-202-14, stick with the 120-day inspection.

Keep inspecting LPUs every 120 days until Air Force changes are incorporated into TM 5-4220-202-14

