


BE PATIENT WITH HEATER



Having trouble with a slow-starting personnel heater, NSN 2540-01-114-7688, on your MLRS carrier?

Could be there's no problem at all. Those heaters come equipped with either an old- or new-style regulator, NSN 2540-12-171-3208. The old style regulators get the fuel pump started immediately. The new-style regulators have a built-in 27-30 second delay before the fuel pump kicks in.

Both regulators work fine, but you just may have to wait a few more seconds for some hot air.

