

# GOT YOUR WARNING DECALS?

**HOLD ON!**

WE'RE NOT DOING ANY FIRING UNTIL YOU PUT ON MY WARNING LABELS!

I DON'T WANT YOU GUYS GETTIN' HURT!

**B**ecause three soldiers recently lost their lives during misfire removals with the M120/M121 mortar, the misfire and PMCS procedures have been changed by Change 3 to TM 9-1015-250-10. If you haven't seen the new procedures, see Pages 22-25 in PS 601 (Dec 02) or ask your TACOM logistics assistance representative to get you a copy. The article is on the Internet at:

[http://www.logsa.army.mil/pub/PSissues/PS\\_601.pdf](http://www.logsa.army.mil/pub/PSissues/PS_601.pdf)

Part of MWO 9-1015-250-30-2 is to add warning decals to the M120/M121 that say: **WARNING! SET SELECTOR LEVER TO SAFE BEFORE ATTEMPTING TO EXTRACT MISFIRED ROUND.** The decals should be put on the cartridge extractor, on each side of the carrier ammo racks, on the rifle rack, and on the underside of the step lid. The decal shows the proper setting for **SAFE**.

If you haven't gotten the decals or you have missing or damaged decals, contact your TACOM LAR or call TACOM-Rock Island's Joe Schmidt at DSN 793-3369/(309) 782-3369 or James Hayes at DSN 793-3229/(309) 782-3229 or email:

**TACOM-RI-Mortar-Systems@ria.army.mil**

MWO 9-1015-250-30-2 also explains where to put the decals on your mortar and TB 9-1015-250-30-1 shows how to replace damaged decals. Your TACOM LAR or TACOM-Rock Island can get you both publications.

