




# Fan Pulley Bearing



**O**perators, you're being too clever by half if you think all the grease fittings on the 815F compactor are out in the open.

The fan pulley bearing is snubbed often because it's out of sight or covered with mud.

The grease fitting for the fan pulley bearing is hidden behind the fan blades. That means it's hard to find, even after you've opened the engine access door (curbside) and looked inside.

Without lube, the fan pulley's bearing will seize up. Then the blade stops turning freely, letting the engine and transmission overheat.

Keep the fan bearing lubed. During scheduled services, give the fitting four or five shots of grease.

