

AVOID THE FUEL CAP FOLLIES

WELCOME
DIRT AND
SAND!

POOR GASKET PM
IS YOUR INVITATION
TO ENTER THE
FUEL TANK!

DIRT
& SAND
ENTER
HERE!

Free
Admission!

Before you screw the fuel cap back in place on your HEMTT, take a look at the cap's gasket, operators.

Dirt and sand around the rim of the filler neck—and just plain old wear and tear—can cut, gouge and wear away the gasket. Enough damage lets dirt, sand and water get inside your fuel tank.

Check
gasket
for
damage



If the gasket's damaged, order a new fuel cap, NSN 2590-01-165-0763. The gasket itself has no replacement.

BRIEFLY
SPEAKING...



HMMWV Turnbutton

NSN 5325-00-823-5999 gets the turnbutton fastener that's used to secure the soft cover to the vehicle's bow enclosures. This NSN replaces the parts info shown as Item 11, Fig 318 of TM 9-2320-280-24P-1.

TURN IN FITS

If your motor pool has a fuel injection pump test stand (FITS), NSNs 4910-01-194-7667 or 4910-01-316-6176, that's no longer needed or is unserviceable, TACOM-Rock Island would like to know about it. They have a contract to upgrade FITS and they need test stands. Contact TACOM-RI at DSN 793-5074 / (309) 782-5074 or email AMSTA-LC-CT@ria.army.mil