



Take It Easy on Fitting



Crewmen, a light touch is important when attaching the fuel line fitting to the A-20 personnel heater on your combat vehicle.

The fitting connects to the fuel manifold, which cracks easily if you're not careful. That means a fuel leak and a fire hazard.

Manifold will crack if fitting is too tight



Operators aren't allowed to remove the cover, so you can't see the damage. The only way you'll know there's a problem is **after** the fuel starts leaking.

So go easy on the fuel line fitting. Sniff with your nose or check with your finger after connecting the fitting to make sure there's no leak.

AZURE BLUE UPDATE

The Azure Blue cannon cleaning kit can be used to clean **only** artillery tubes. That includes the M198 and M119A1/A2 towed howitzers and M109-series SP howitzers. **Do not** use the kit to clean the crew compartment of M109-series SP howitzers. **Do not** use the kit for any type of cleaning on M1-series tanks or any mortar system.