

Too Many Hits

YOUR MISSION'S OVER, BUT YOU **SHOULDN'T** HAVE SLUNG YOUR SEATBELT!

YOU DAMAGED MY AN/ARC-220 LCD PANEL.

SORRY, I FORGOT TO COVER YOUR LCD PANEL.



Dear Rotor,

Our Black Hawk unit recently received AN/ARC-220 high frequency radios.


After a few months, we noticed small cracks and dark blemishes on some of the LCD displays in the center control panel.

This is the result of careless slinging, dropping and flipping of the seat belt to the left after unfastening the buckle.

After too many hits, the LCD panel becomes unreadable. Replacing the ARC-220 high frequency control costs the unit \$5,287, minus the \$2,882 unserviceable credit. We pay a whopping \$2,405 every time the ARC-220 HF radio control head, NSN 5821-01-413-4243, gets damaged.

SSG D. H.
1022 Med Co.
Cheyenne, WY

Do not drop or sling belt on LCD panel



Dear Sergeant D. H.,

To protect the LCD panel, otherwise called the optical window instrument, and save maintenance costs, order a LCD panel cover with NSN 6650-01-519-9165. That should cover the problem.

Rotor Blade

Place cover on LCD panel for protection

