


# TURN IN UNSERVICEABLE PARTS



**T**he demand for long range advanced scout surveillance system (LRAS3) infrared night vision sight (AN/TAS-8) repair parts is high, but the turn-in of unserviceable parts is low.

Unserviceable parts are only unserviceable to you, the user. They are fixed at depot and reissued! But they can't be fixed and reissued if you don't turn them in.

So search your shelves and drawers for those unserviceable parts.



LOOK LONG AND HARD FOR THESE PARTS THAT ARE CRITICALLY SHORT...

**Circuit cards** NSN 5998-01-486-

5004

5005

5019

5020

5021

**Laser rangefinder** NSN 1240-01-

486-5003

506-8841

**Laser optical assembly** NSN 5860-01-

486-5044

506-8843

**Infrared lens**, NSN 5855-01-486-5022

**Display unit**, NSN 7025-01-486-5024

**Adapter assembly**, NSN 4920-01-486-5029

**Adapter assembly**, NSN 4920-01-494-5187

**Adapter assembly**, NSN 4920-01-486-5040

**Electrical panel**, NSN 5975-01-486-5035

**Tripod mount leg**, NSN 1020-01-486-5041

**Inclinometer**, NSN 6605-01-486-6395

**Housing**, NSN 5999-01-486-6396

**Housing**, NSN 5999-01-494-3670

**Housing**, NSN 5999-01-518-8796

**Housing**, NSN 5999-01-518-8833