

Replace Worn Strap



Desert conditions have turned the original troop seat stowage straps on some FMTVs into rags.

If the straps on your trucks show signs of brittleness, cuts, tears or shredding, don't go looking for the replacement information in your truck's -24P.

What will be added to Fig 232 in both FMTV -24Ps is a belt, NSN 2540-01-438-5919. It's 1½ inches wide with a quick-disconnect fastener. It must be riveted to the troop seat.

BATTERY BOX LINER

Battery box liner works finer than anything else for absorbing battery acid in your vehicle's battery box.

The liner not only absorbs battery acid, but neutralizes it as well.

Get a roll of 1/4-in thick liner with NSN 6160-01-389-1966 and cut to the dimensions you need to line a vehicle's battery box.

