

M1070 HET, M1074/M1075 PLS...

# STUD KIT SEALS THE DEAL



## KOFF-KOFF

You're not talking "chump change" when it comes to buying a new air cleaner assembly for an M1070 HET or M1074 or M1075 PLS truck.

Since they're not cheap, it's tough to replace an assembly just because a mounting stud is damaged or missing.

Keep the seal between the air cleaner mount and the element container (housing) tight by using stud replacement kit, NSN 5307-01-456-6938.

