


TIGHT AND SECURE



Mechanics, a loose or dangling protective cap for the coolant fill port on your Kiowa Warrior's mast mounted sight (MMS) could mean trouble later.

During flight a loose cap can come off, flail around on the lanyard, and hit the side of the turret and the lightning protective tape. That can damage the turret frame and the tape with dents, gouges, or pits.

So, after servicing your MMS make sure the protective cap is seated correctly and tight and that the lanyard is securely attached.

