

Replace M-1941, M-1950 Space Heaters... NOW!

ADIOS, OLD TIMERS... IT'S TIME FOR YOUR RETIREMENT!

WAIT A MINUTE! YOU GUYS DON'T LOOK MUCH DIFFERENT FROM US...

WHAT'S THE BIG DEAL?

WE MAY LOOK LIKE YOU, BUT WE'RE NEW AND IMPROVED!





If you're still running the old M-1941 or M-1950 space heaters, turn them in now. These heaters are inefficient and unsafe to operate. What's more, the Army has no spare parts for them.

Replace the M-1941 with the H-45 space heater, NSN 4520-01-329-3451, made for use in the general purpose and TEMPER tents.

Replace the M-1950 with the arctic space heater, NSN 4520-01-444-2375, made for use in the 5-man and 10-man arctic tents.

Both the H-45 and the arctic heaters are members of the family of space heaters (FOSH). Although there's no Army-wide policy letter ordering replacement, several local policy letters order it.



FOR MORE INFORMATION ON FOSH, GO TO THE DEFENSE SUPPLY CENTER PHILADELPHIA WEBSITE:
<http://www.dscpc.dla.mil/gi/general/fosh.htm>

