




Unserviceable M2A2 Aiming Circles Needed Now!



THE **ONLY** WAY TO MEET THIS DEMAND IS WITH REFURBISHED M2A2s.



YOU CAN ORDER A REPLACEMENT M2A2 WITH NSN 6675-01-067-0687. DUE TO THE M2A2 SHORTAGE, THE ARMY CAN'T OFFER A DIRECT EXCHANGE REPLACEMENT.



WHEN YOU TURN IN AN AIMING CIRCLE, REMEMBER IT INCLUDES THESE ITEMS...



- aiming circle transit, NSN 1290-01-510-0540
- access cover, NSN 5340-00-346-8171
- lamp extractor, NSN 5120-00-505-5477
- instrument light, NSN 6695-00-346-8186
- tarpaulin, NSN 2540-00-346-8147
- access cover, NSN 5340-00-346-8177
- plumb bob assembly, NSN 1290-00-346-8185
- fire control assembly tripod, NSN 1290-00-346-8184
- incandescent lamp, NSN 6240-00-635-9800
- TM 9-1290-262-10 and TM 9-1290-262-HR

FOR SHIPPING INSTRUCTIONS, CALL TACOM'S AIMEE WREN AT DSN 793-5321/(309) 782-5321; FAX DSN 793-1931/(309) 782-1931 OR EMAIL: aimee.j.wren@us.army.mil



M9 Pistol... **MAGAZINES WITH CORRECT COATING?**



Dear Half-Mast,
We received a message that we needed to replace the magazines for our M9 pistols because they had the wrong coating. But we can't find the NSN for the new magazines. Can you help?

SSG N. B.

Dear Sergeant N.B.,
Sure can. Use the same NSN as the NSN for the bad magazines: 1005-01-204-4376. It will bring you magazines with the right coating this time. It should have "May 04" stamped on it or the contract paperwork should show "04".

Half-Mast