


CHECK FOR WRONG SOCKET SET



Some SECMs (shop equipment, contact maintenance) were fielded with a standard length $\frac{3}{8}$ -in drive metric socket set that's wrong. They should have, in Drawer CB4, a $\frac{3}{8}$ -in drive metric deep socket set (8mm through 19mm), which has deeper sockets.

Check the data plate on the rear of the SECM shelter for one of these serial numbers:

208752	209063	209122
208946	209066	209123
209022	209070	209131
209035	209082	209135
209039	209087	209146
209043	209091	209151
209046	209107	209154
209047	209115	209162
209054	209119	

If your SECM has one of these numbers, you have the wrong socket set. Contact your local TACOM logistics assistance representative or state surface maintenance manager for help getting the correct set.

Or you can contact TACOM-Rock Island at DSN 793-4674/(309) 782-4674 or email:

lori.leebold@us.army.mil

You will receive a new socket set and a foam insert to hold the tools in the drawer. Keep the old socket set to use as spares.

