



HMMWVs...

# UNDERBODY ARMOR CAN MAKE TRUCK NMC



When the mission requires you to take your M1113, M1114, M1116, or M1145 HMMWV into hostile territory, you don't want any problems! That means a careful PMCS using TM 9-2320-387-10.

But, there's been a change to NMC criteria for the underbody armor. On Page 2-54, Table 2-2, Item 44g, the **Not Fully Mission Capable If** column should be changed to say: "Vehicle has a loose or missing retainer plate or bolt in positions 1 and 5 from either side. Loose or missing more than three bolts in positions 2, 3, and 4 from either side or missing more than one retainer plate in positions 2, 3, and 4 from either side." Make a note of the new NMC criteria until the TM is updated.



The TM also tells you that PMCS intervals must be performed **more frequently** when operating under unusual conditions. What's more frequently? It's recommended that **Before and After** PMCS inspections be done for the underbody armor before and after **every** trip outside the fence! Take the time to do so, and you'll be safer.