

HMMWV BRAKE PADS COULD BE BAD



SOMETIME LATER...



About 4,000 defective brake pads have mistakenly been issued to the field. Defective brake pads can pose a serious safety hazard by leading to degraded braking capability, wheel lock-up, loss of control, or an accident—things you want to prevent!


If your HMMWV uses brake pads, NSN 2530-01-420-8025, inspect them right away. A photo of these oversized, non-conforming brake pads can be viewed online:

https://aeps2.ria.army.mil/commodity/soum/tacom_wn/06/hmmwv-brake-shoe.doc

If your brake pads and label look like this, **don't** use the brake pads.



2530014208025
NSN 2530-01-420-8025
CAGE: 06YZ5 P/N: BXXM2FF
BRAKE SHOE SET
1 SE
SP0750-04-C-3486
M31-06/04



If you find defective brake pads, remove them, hold them for exhibit, and replace them with new pads. For more details, read TACOM SOUM 06-014:

https://aeps2.ria.army.mil/commodity/soum/tacom_wn/06/soum06-014.html